

# COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE

Vehicle No.: SHC1160D  
 Make : TOYOTA  
 Model : PRIUS  
 DOA : 12.04.2022

Date : 13.04.2022  
 Insurance: NTUC  
 MVA : CHIANG  
 Admin :

Part No.	Parts Description / Labour	Qty	Unit Price	Amount
1	REAR TRUNK LID LOGO (PRIUS)			\$69.32 <i>nec</i>
1	REAR TRUNK LID LOGO (HYBRID)			\$62.14 <i>nec</i>
1	REAR TRUNK LID LOGO (TOYOTA STAR)			\$81.43 <i>nec</i>
1	REAR BUMPER			\$503.04 <i>ht</i>
1	REAR BUMPER UNDER COVER			\$654.96 <i>X Svc</i>
1	REAR BUMPER SIDE RETAINER LH/RH		\$112.70	\$225.40 <i>nec</i>
1	REAR BUMPER SIDE UNDER RH			\$108.00 <i>ht</i>
1	TAILLAMP LOWER RH			\$570.00 <i>Sc</i>
1	REAR TOW COVER			\$98.80 <i>X Svc</i>
1	FENDER AIR DUCT			\$165.10 <i>X Svc</i>
1	REAR BUMPER CLIPS			\$22.00 <i>nec</i>
10	REAR BUMPER REINFORCEMENT			\$378.32 <i>X Svc</i>
	<b>SUB TOTAL</b>			\$2,938.51
	<b>LESS 25%</b>			\$734.63
	<b>DISCOUNTED TOTAL</b>			<b>\$2,203.88</b>
1	REAR BUMPER MAT			\$50.00 <i>nec</i>
2	REAR FENDER ADVERTISEMENT		\$100.00	\$200.00 <i>nec</i>
1	REAR TRUNK LID APPS STICKER			\$40.00 <i>nec</i>
1	REAR TRUNK LID COMFORT & TEL NO. STICKER			\$60.00 <i>nec</i>
1	REAR BUMPER REVERSE SENSOR			\$135.70 <i>X Svc</i>
				<b>\$485.70</b>
	<b>Labour Charge</b>			
	Panel Beating			\$875.00 <i>700</i>
	Spray Painting Charge			\$750.00 <i>500</i>
	Wiring Charge			\$60.00 <i>30</i>
	Tuff Kote			\$90.00 <i>30</i>
	Remove/Refix Reverse Sensor			\$60.00 <i>30</i>
	<b>TOTAL LABOUR</b>			<b>\$1,835.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$4,524.58</b>

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Our survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Thuan  
 82235969  
 16/4/22 1619  
 3  
 L/S repair 30 days