

ASS. REC. BY: ThuvanREF: Ntuc NS/INC22003744/Vvc**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: FBR 7996L

Policy No. _____


Claims No. MT/1170836-001

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHC1160 D Yr Regn: 6/10 117Type: M.Car / M.Cycle / Bus / Van / Lorry / (Taxi) Prime Mover /

Truck / Trailer or

Make: Toyota prius c.c 1798Colour blue A/C: Insured / Std / NI / NASp.Reading 552500 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 5 + DHB3Fu503568953Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: NII / S/Rim / STD A/Rim orTyre Size: F: 195/65R15R: 195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front

Rear

R/Bal. 5 mm R/Bal. 5 mmL/Bal. 5 mm L/Bal. 5 mmD.O.A. 12/11/22 D.O.I. 13/11/22 1615Survey held at CDGIEDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>NO GIFT provided</u>
26/4/22	Thevan informed LS \$2200 (red 2324.58, 51%)

Date/Time, File Pass to?

☐ : Prell. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 5/5/22-typistDays Of Repair: 3Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

___ S + RS, ___ SI

Photos

Others

TOTAL

Report Format : TPLump Sum / L.B. (\$ 2200)

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Vehicle No.: SHC1160D
 Make : TOYOTA
 Model : PRIUS
 DOA : 12.04.2022

Date : 13.04.2022
 Insurance: NTUC
 MVA : CHIANG
 Admin :

Part No.	Parts Description / Labour	Qty	Unit Price	Amount
1	REAR TRUNK LID LOGO (PRIUS)			\$69.32 <i>nec</i>
1	REAR TRUNK LID LOGO (HYBRID)			\$62.14 <i>nec</i>
1	REAR TRUNK LID LOGO (TOYOTA STAR)			\$81.43 <i>nec</i>
1	REAR BUMPER			\$503.04 <i>ht</i>
1	REAR BUMPER UNDER COVER			\$654.96 <i>X Svc</i>
1	REAR BUMPER SIDE RETAINER LH/RH		\$112.70	\$225.40 <i>nec</i>
1	REAR BUMPER SIDE UNDER RH			\$108.00 <i>ht</i>
1	TAILLAMP LOWER RH			\$570.00 <i>scr</i>
1	REAR TOW COVER			\$98.80 <i>X Svc</i>
1	FENDER AIR DUCT			\$165.10 <i>X Svc</i>
10	REAR BUMPER CLIPS			\$22.00 <i>nec</i>
1	REAR BUMPER REINFORCEMENT			\$378.32 <i>X Svc</i>
	SUB TOTAL			\$2,938.51
	LESS 25%			\$734.63
	DISCOUNTED TOTAL			\$2,203.88
1	REAR BUMPER MAT			\$50.00 <i>nec</i>
2	REAR FENDER ADVERTISEMENT		\$100.00	\$200.00 <i>nec</i>
1	REAR TRUNK LID APPS STICKER			\$40.00 <i>nec</i>
1	REAR TRUNK LID COMFORT & TEL NO. STICKER			\$60.00 <i>nec</i>
1	REAR BUMPER REVERSE SENSOR			\$135.70 <i>X Svc</i>
				\$485.70
	<u>Labour Charge</u>			
	Panel Beating			\$875.00 <i>700</i>
	Spray Painting Charge			\$750.00 <i>500</i>
	Wiring Charge			\$60.00 <i>30</i>
	Tuff Kote			\$90.00 <i>30</i>
	Remove/Refix Reverse Sensor			\$60.00 <i>30</i>
	TOTAL LABOUR			\$1,835.00
	ESTIMATE TOTAL			\$4,524.58

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Thuan
 82235969
 16/4/22 1619
 3
 L/S repair 30 days

Date/Time: 13.04.2022 13:15 Page : 1

Team: ARC Repair TP(CLS0)1

JOB CARD Sales Order: 4196402


JC NO.305512228

CUSTOMER VMS CUSTOMER NO ADDRESS L. (R) (P)	COMFORT TRANSPORTATION PTE LTD 7010045 383 SIN MING DRIVE Singapore SINGAPORE 575717 65508755		REGN NO: SHC1160D	MILEAGE
			MAKE: TOYOTA	FUEL E.....1/2.....F
			MODEL PRIUS HYBRID(G4)13	DATE/TIME IN 04.2022 10:50
			YR OF MANU 06.10.2017	TARGET DATE
			CHASSIS CODE JTDKB3FU503568953	COMPLETION DATE/TIME:
SCOUNT CARD NO.				

JOB DESCRIPTION

Accident Date: 12.04.2022
NATURE: 3P 12.04.2022

S/NO LABOR CODE DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Vehicle No.: SHC1160D CHIANG

Vehicle No.: SHC1160D

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard