

Our Job Ref No : 305512228
Date : 21.04.2022

COMFORTDELGRO
ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969

FINALIZATION FORM

To : LKK

Fax :

Attn : THEVAN

Vehicle Reg No. : SHC1160D

12.04.2022

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

Z The repair job shall bill to: NTUC FBR7996L

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges

Total for Part-By-Part Repair Cost

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: \$2,200.00

Final Lumpsum Repair cost

3. Estimated normal period for repairs: 3 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.


We confirm the estimates and finalized amount

Signature : 

Name : CHIANG

Tel : 62148314

Fax : 65468156

Signature : 

Name : THEVAN

Date : 26/4/22

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	-	N		
3. Survey Fees	-	-		
4. LTA Search Fee	\$7.49/\$2.00	YES		
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Vehicle No.: SHC1160D
 Make : TOYOTA
 Model : PRIUS
 DOA : 12.04.2022

Date : 13.04.2022
 Insurance: NTUC
 MVA : CHIANG
 Admin :

Part No.	Parts Description / Labour	Qty	Unit Price	Amount
				\$69.32 <i>nec</i>
1	REAR TRUNK LID LOGO (PRIUS)			\$62.14 <i>nec</i>
1	REAR TRUNK LID LOGO (HYBRID)			\$81.43 <i>nec</i>
1	REAR TRUNK LID LOGO (TOYOTA STAR)			\$503.04 <i>ht</i>
1	REAR BUMPER			\$654.96 <i>X Svc</i>
1	REAR BUMPER UNDER COVER		\$112.70	\$225.40 <i>nec</i>
1	REAR BUMPER SIDE RETAINER LH/RH			\$108.00 <i>ht</i>
1	REAR BUMPER SIDE UNDER RH			\$570.00 <i>Scr</i>
1	TAILLAMP LOWER RH			\$98.80 <i>X Svc</i>
1	REAR TOW COVER			\$165.10 <i>X Svc</i>
1	FENDER AIR DUCT			\$22.00 <i>nec</i>
10	REAR BUMPER CLIPS			\$378.32 <i>X Svc</i>
1	REAR BUMPER REINFORCEMENT			\$2,938.51
	SUB TOTAL			\$734.63
	LESS 25%			\$2,203.88
	DISCOUNTED TOTAL			
				\$50.00 <i>nec</i>
1	REAR BUMPER MAT		\$100.00	\$200.00 <i>nec</i>
2	REAR FENDER ADVERTISEMENT			\$40.00 <i>nec</i>
1	REAR TRUNK LID APPS STICKER			\$60.00 <i>nec</i>
1	REAR TRUNK LID COMFORT & TEL NO. STICKER			\$135.70 <i>X Svc</i>
1	REAR BUMPER REVERSE SENSOR			\$485.70
	<u>Labour Charge</u>			
	Panel Beating			\$875.00 <i>700</i>
	Spray Painting Charge			\$750.00 <i>500</i>
	Wiring Charge			\$60.00 <i>30</i>
	Tuff Kote			\$90.00 <i>30</i>
	Remove/Refix Reverse Sensor			\$60.00 <i>30</i>
	TOTAL LABOUR			\$1,835.00
	ESTIMATE TOTAL			\$4,524.58

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - This survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Thuan
 82235969
 16/4/22 1613
 3
 L/S repair 30daySwp