

REPAIR ESTIMATE

Effective Date: 1 Nov 2020

DATE: 13.04.22

LKK -

MODEL: Hyundai Ioniq

INSURANCE: NTUC (LIS)

VEHICLE NO.: SH 4301M

MVA: LIM T S

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Rear Bumper	1		\$ 459.40
	Rear Bumper Centre Moulding	1		\$ 451.25
	Rear Bumper Reflector LH	1		\$ 41.45
	Rear Bumper Retainer LH	1		\$ 55.80
	Rear Bumper Clips	10	\$ 2.20	\$ 22.00
	Rear Wheel Cap LH	1		\$ 346.40
	Rear Door LH	1		\$ 2,147.90
	Rear Door Protector LH	1		\$ 166.20
	Rocker Panel Garnish LH	1		\$ 290.00
	SUB TOTAL			\$ 3,980.40
	LESS 20%			\$ 796.08
	SPARE PARTS TOTAL			\$ 3,184.32
	Rear Fender (Petrol Only) LH	1		\$ 40.00
	Rear Door Apps Sticker LH	1		\$ 80.00
	Rear Bumper Mat	1		\$ 50.00
	NETT TOTAL			\$ 170.00
	Labour Charge			
	Panel Beating - Rear Fender Arch LH			\$ 800.00
	Spray Painting Charge			\$ 1,200.00
	Chek Wirings			\$ 40.00
	Tuff Kote			\$ 80.00
	Transfer Of Door			\$ 120.00
	R/I Reverse Sensors			\$ 120.00
	TOTAL LABOUR			\$ 2,360.00
	ESTIMATE TOTAL			\$ 5,714.32

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Thucm

82235769

13/4/22 1600

LIS 3da 3days w p

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: