

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI22003748/VQY3N2**Date:** 24/05/2022REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd

Policy No: MR003352

Claimant Vehicle No : SHC2446Z**Insured Vehicle No :** SMT5356G

Date of Loss: 21/04/2022

Nature of Claim: TP Claim No: M2201895

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SHC2446Z**

Make & Model: TOYOTA PRIUS, 1.5 HYBRID (A)

Engine No: 2ZR2B93441

Reg. Date: 05/03/2019 (Man. Year: 2018)

Chassis No: JTDKB3FU403078665

Colour: Blue

Odometer: 482353 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: West Lake 5 mm

Rear Left Side: West Lake 5 mm

Front Right Side: West Lake 5 mm

Rear Right Side: West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,239.79	1,956.05	283.74	12.67
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,470.00	910.00	560.00	38.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,720.79	2,877.05	843.74	22.68
Approved Total (Overridden) (S\$)		2,300.00		
(S\$)	3,720.79	2,300.00	1,420.79	38.19
+ GST 7.00/7.00% (S\$)	260.46	161.00	99.46	38.19
Nett Amount (S\$)	3,981.25	2,461.00	1,520.25	38.19

INSPECTION

Date of Assignment:	22/04/2022	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	22/04/2022	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days		

Adjuster: Thevan Thomas Karthikesavan**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 May 2022)
Parts:	144	TOYOTA PRIUS 1.5 HYBRID (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC2446Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Reference	Amount
1	1	*REAR BUMPER	Cut	503.04 FL	-	*503.04 FL
2	1	*REAR BUMPER CLIPS	Necessary	22.00 FL	-	*22.00 FL
3	1	*REAR BUMPER LOWER COVER	Scratched	654.96 FL	-	*654.96 FL
4	1	*REAR BUMPER TOWING COVER	Missing	82.70 FL	-	*82.70 FL
5	1	*REAR BUMPER SIDE RETAINER RH	Necessary	112.70 FL	-	*112.70 FL
6	1	*REAR BUMPER REINFORCEMENT	Serviceable	378.32 FL	-	*- FL
7	1	*REAR BUMPER SIDE EXTENTION RH	Cut	148.40 FL	-	*148.40 FL
8	1	*TAIL LAMP LOWER RH	Cracked	570.00 FL	-	*570.00 FL
9	1	*REAR REVERSE SENSOR	Cut	135.70 F	-	*135.70 FS
10	1	*REPLACE REAR BUMPER ADVERTISEMENT LOGO	Necessary	50.00 F	-	*50.00 FS
11	1	*REPLACE REAR FENDER ADVERTISEMENT LOGO LH	Necessary	100.00 F	-	*100.00 FS
12	1	*REPLACE REAR FENDER ADVERTISEMENT LOGO RH	Necessary	100.00 F	-	*100.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	2,857.82	2,479.50
- List Item Discount on L Items 25.00/25.00% (\$)	618.03	523.45
Total Parts (\$)	2,239.79	1,956.05

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	550.00	350.00
2	SPRAY PAINTING CHARGE	New	800.00	500.00
3	CHECK ALL LIGHTING	New	60.00	30.00
4	REMOVE/REFIX REVERSE SENSOR	New	60.00	30.00
Gross Labour Cost (\$\$)			1,470.00	910.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >