

Our Job Ref No : 305513209
Date : 26/04/22

**COMFORTDELGRO
ENGINEERING**

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK
Attn : Mr Thevan
Vehicle Reg No. : SHC2446Z


Fax :


21/04/2022

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: **TOKIO MARINE** --- **SMT5356G**
2. The finalized amount shall be:
 - (a) Spare Parts after List discount
 - (b) Labour Charges
 - Total for Part-By-Part Repair Cost** **\$0.00**
 - (c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20%
Final Lumpsum Repair cost **\$2,300.00**
3. Estimated normal period for repairs: **2** working days.
4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 
Name : Ms. Loke YY
Tel : 62148355
Fax : 65468156

Signature : 
Name : Thevan
Date : 28/4/22

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

REPAIR DETAILS**Reference**

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 21 Apr 2022)

Parts: 144 **TOYOTA PRIUS 1.5 HYBRID (A) (Catalogue:Merimen Singapore 1.0)**

Labour: Repairer's **(Price-denominated Standard List)**

Print Code: ComfortDelGro Engineering Pte Ltd/SHC2446Z/21/04/2022 14:10

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER	25.00	0.00	*503.04 FL
2	1		*REAR BUMPER CLIPS	25.00	0.00	*22.00 FL
3	1		*REAR BUMPER LOWER COVER	25.00	0.00	*654.96 FL
4	1		*REAR BUMPER TOWING COVER	25.00	0.00	*82.70 FL
5	1		*REAR BUMPER SIDE RETAINER RH	25.00	0.00	*112.70 FL
6	1		*REAR BUMPER REINFORCEMENT	25.00	0.00	*378.32 FL
7	1		*REAR BUMPER SIDE EXTENTION RH	25.00	0.00	*148.40 FL
8	1		*TAIL LAMP LOWER RH	25.00	0.00	*570.00 FL
9	1		*REAR REVERSE SENSOR	0.00	0.00	*135.70 F
10	1		*REPLACE REAR BUMPER ADVERTISEMENT LOGO	0.00	0.00	*50.00 F
11	1		*REPLACE REAR FENDER ADVERTISEMENT LOGO LH	0.00	0.00	*100.00 F
12	1		*REPLACE REAR FENDER ADVERTISEMENT LOGO RH	0.00	0.00	*100.00 F

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	2,857.82
- List Item Discount on L Items (S\$)	618.03
Total Parts (S\$)	2,239.79

ComfortDelGro Engineering Pte Ltd/SHC2446Z/21/04/2022 14:10. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1 1 OD/TP Case (Insurer)

11.00

Sub Total (\$\$)

11.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1 PANEL BEATING

New

550.00 350

2 SPRAY PAINTING CHARGE

New

800.00 500

3 CHECK ALL LIGHTING

New

60.00 30

4 REMOVE/REFIX REVERSE SENSOR

New

60.00 30

Gross Labour Cost (\$\$)

1,470.00

ComfortDelGro Engineering Pte Ltd/SHC2446Z/21/04/2022 14:10. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Thuan
82235769
22/4/22 1600
L/S 2day swp

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: