

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22003753/ANY3M4**Date:** 08/07/2022REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNA00042962201	
<b>Claimant Vehicle No :</b>	SNE8784B	<b>Insured Vehicle No :</b>	SMV5789E	
Date of Loss:	20/04/2022	Nature of Claim:	TP	Claim No: SNM22D202680/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SNE8784B</b>		Engine No:	65492080975736
Make & Model:	MERCEDES-BENZ E220D SE, 2.0 (A)		Chassis No:	W1K2130042A897950
Reg. Date:	18/04/2022 (Man. Year: 2021)		Odometer:	389 km
Colour:	Black			
Engine Capacity:	1950 cc			
Market Value/New Car Price:	N/A			
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/45 R18	Rear Tyre Size:	245/45 R18
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

*The above values represent the remaining tyre tread depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	11,637.40	3,965.00	7,672.40	65.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,830.00	1,630.00	2,200.00	57.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>15,467.40</b>	<b>5,595.00</b>	<b>9,872.40</b>	<b>63.83</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>4,450.00</b>		
<b>(\$\$)</b>	15,467.40	4,450.00	11,017.40	71.23
<b>+ GST 7.00/7.00% (\$\$)</b>	1,082.72	311.50	771.22	71.23
<b>Nett Amount (\$\$)</b>	<b>16,550.12</b>	<b>4,761.50</b>	<b>11,788.62</b>	<b>71.23</b>

INSPECTION

Date of Assignment:	22/04/2022	My Car Consultant Pte Ltd ( Jalan Lam Huat ) (HQ) 60 Jalan Lam Huat, Carros Centre #05-21 Singapore 737869
Date Inspected:	22/04/2022 Inspected At:	
Estimated Period of Repair:	5.0 days	

**Adjuster:** ADRIAN LING**Manager:** HUEY YON

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 07 Jul 2022)

**Parts:** 143      MERCEDES-BENZ E220D SE 2.0 (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's      (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SNE8784B)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER RH	Dented	1,025.00 FL	*1,025.00 FL
2	1		*FRONT FENDER COWLING	Not Necessary	321.00 FL	*- FL
3	1		*FRONT DOOR RH	Dented	2,567.00 FL	*2,200.00 FL
4	1		*FRONT DOOR OUTER MOULDING	Not Necessary	189.00 FL	*- FL
5	2		*FRONT DOOR HINGES	Not Necessary	224.00 FL	*- FL
6	1		*SIDE MIRROR RH	Damaged	1,125.00 FL	*1,125.00 FL
7	1		*SIDE SKIRTING RH	Repair	1,258.00 FL	*- FL
8	1		*REAR FENDER RH	Repair	1,598.00 FL	*- FL
9	1		*REAR BUMPER	Repair	1,985.00 FL	*- FL
10	1		*SET REAR BUMPER CLIP	Necessary	60.00 FS	*50.00 FS
11	1		*REAR WHEEL SPORTS RIM RH	Not Necessary	1,800.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>12,152.00</b>	<b>4,400.00</b>
<b>- List Item Discount on L Items 5.00/10.00% (\$\$)</b>	514.60	435.00
<b>Total Parts (\$\$)</b>	<b>11,637.40</b>	<b>3,965.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO PANEL BEAT, WELD, CUT, KNOCK STRAIGHTEN, ADJUST GRAZE, JOIN	New	1,000.00	500.00
2	TO PUTTY, SPRAY PAINT, POLISH, WAX AFFECTED PARTS AND PANELS	New	1,200.00	1,000.00
3	NANO COATING	New	400.00	0.00
4	WIRING CHECK	New	600.00	30.00
5	REMOVE AND REFIX SIDE MIRROR	New	150.00	0.00
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	180.00	0.00
7	REMOVE AND REFIX FRONT DOOR MECHANISM	New	180.00	100.00
8	CONDUCT WHEEL ALIGNMENT	New	120.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,830.00</b>	<b>1,630.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >