

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS3/CTI22003756/GQY3N2**Date:** 28/04/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMB1SNW00013162101

**Claimant Vehicle No :** SJM2387J **Insured Vehicle No :** PC1716G

Date of Loss: 19/04/2022 Nature of Claim: TP Claim No: SNM22D202707/CO2/LEWLC

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SJM2387J**

Make & Model: CHEVROLET AVEO 4, 1.4 (A) Engine No: HIDDEN

Reg. Date: (Man. Year: ) Chassis No: 0

Colour: Silver Odometer: 140098 km

Engine Capacity: 1399 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 185/60R14 Rear Tyre Size: 185/60R14

Front Left Side: Tourador 6 mm Rear Left Side: Tourador 6 mm

Front Right Side: Tourador 6 mm Rear Right Side: Tourador 6 mm

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>     | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|---------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                     | 0.00              | 0.00              | 0.00              |               |
| Miscellaneous Items       | 0.00              | 0.00              | 0.00              |               |
| Labour                    | 0.00              | 0.00              | 0.00              |               |
| Paintwork Labour          | 0.00              | 0.00              | 0.00              |               |
| Towing                    | 0.00              | 0.00              | 0.00              |               |
| <b>Nett Amount (\$\$)</b> | <b>0.00</b>       | <b>0.00</b>       | <b>0.00</b>       |               |

**INSPECTION**

Date of Assignment: 22/04/2022

Date Inspected: 25/04/2022 Inspected At: A-Tec Automotive Pte Ltd (Kaki Bukit)  
8 Kaki Bukit Ave 4, #04-20 Premier  
Singapore 415875

Estimated Period of Repair: 4.0 days

**Adjuster:** XING GUO QIANG**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00  
-\$4,000.00

REPAIR DETAILS

|               |                                                                                                                                                                              |                                                            |
|---------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------|
| Reference     |                                                                                                                                                                              |                                                            |
| Part Source:  | MRM-SG                                                                                                                                                                       | Version: 1.0 (Last Synchronised: 26 Apr 2022)              |
| Parts:        | 143                                                                                                                                                                          | CHEVROLET AVEO 4 1.4 (A) (Catalogue:Merimen Singapore 1.0) |
| Labour:       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                          |
| Print Code:   | (Unsubmitted, no print-code for SJM2387J)                                                                                                                                    |                                                            |
| Validity:     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                            |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                            |

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >