

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 3063/04/22 Your Ref: Date: 21st April 2022

MR HO KUM CHUEN
BLK 648, #10-3351
ANG MO KIO AVE 5,
SINGAPORE 560648

Estimate cost of repair to HYUNDAI AVANTE 1.6 (A) Saloon - SJR 5067 L

1 pc rear bumper		\$ 498.00
10 pcs rear bumper clips	@ \$ 3.50	35.00
1 pc rear bumper o/s side retainer		29.00
3 pcs rear bumper o/s inner shield clips	@ \$ 3.50	10.50
1 pc rear o/s fender		1,806.00
6 pcs rear o/s fender inner shield clips	@ \$ 3.50	21.00
1 pc rear o/s door		1,743.00
16 pcs rear o/s door inner trim board clips	@ \$ 5.50	88.00
1 pc rear o/s lower arm		239.00
1 pc rear o/s shock absorber shaft		232.00
1 set rear o/s wheel bearing & hub		395.00
		\$ 5,096.50
	Less 20%	\$ 1,019.30
		\$ 4,077.20
1 pc rear o/s sport rim		650.00 S.N
1 pc rear o/s wheel tyre (195X65XR15)		400.00 S.N
To wiring check up for affected wiring system.		50.00
To check & adjust wheel balancing & wheel alignment.		150.00
To remove & refix rear o/s shock absorber shaft, lower arm, wheel bearing & necessary parts.		220.00
To remove & refix carpet, floor mat, rear o/s fender inner garnish, rear o/s door inner trim board cover for repair.		180.00
Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out rear o/s door & necessary parts, to weld, renew & align above parts.		1,350.00
To putty & respray painting on all affected accident parts.		1,500.00
To respray Tuff-Kote on all affected accident parts.		80.00
		\$ 8,657.20
		=====

Dollars : Eight Thousand Six Hundred Fifty Seven And Cents Twenty Only.

HUP MOTOR TRADING & SERVICE

.....
.....