



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22003758/Any3m4 Date: 14/07/2022 Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	FBM 5589T	Veh. Inspected	SFB 2112R
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2201374/THE	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	22/04/2022
2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ E 250	c.c	1796
	Engine No.	HIDDEN	Year of Reg.	2011
	Chassis No.	WDD2120472A398935	Colour	GREY
	Odometer	176587 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	245/45 R17	TRIANGLE	6 mm
	L/H Front Tyre	245/45 R17	TRIANGLE	6 mm
	R/H Rear Tyre	245/45 R17	TRIANGLE	6 mm
	L/H Rear Tyre	245/45 R17	TRIANGLE	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	20/04/2022	Inspection Date	25/04/2022
	Survey held at	PEOPLE'S VEHICLE RECOVERY SERVICE BLK 3023-A, UBI ROAD 1 #01-60 SINGAPORE 408717		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	