

PEOPLE'S VEHICLE RECOVERY SERVICE

BLK 3023-A UBI ROAD 1 #01-60 SINGAPORE 408717
Tel No. : 67433246 / 67438552 Fax No. : 67430013
E-Mail : peoplevehicle@gmail.com
Tax Reg. No. : M90001895E Buss. Reg. No. : 31800200X

SOMPO INSURANCE (S) PTE LTD
50 RAFFLES PLACE #05-01/06
S'PORE LAND TOWER 048623

Attention : Motor Claim Department
Contact : 6461 6555 Fax No. : 6221 3147

Estimate : ES22007

Date : 25/04/2022
Vehicle Num. : SFB 2112 R
Make/Model : MERCEDES BENZ E250
Chassis/Eng# :
Accident Date : 20/04/2022
Claim No. : TP 415-22
Reference : FBM 5589 T
Policy No. : EQ DMPHQ22-002710

S/N	Quantity	Particular	Unit Price	Amount S\$
1.	1	NETT ITEMS :		
2.	1	BUMPER REAR <i>Distorted</i>		✓ 1,550.00
3.	2	BUMPER CHROME MOULDING REAR <i>3 New</i>		✓ 130.00
4.	2	BUMPER SIDE MOULDING REAR		✓ 230.00
		BUMPER SIDE RETAINER REAR <i>new</i>		✓ 190.00
		Nett Total S\$:		2,100.00
		10.00% Discount S\$:		210.00
				1,890.00

LABOUR :
REMOVE & REPLACE ACCIDENT DAMAGED PARTS
SPRAY PAINTING ACCIDENT AFFECTED PARTS
Labour Total S\$:

500
~~400.00~~ - 250
~~300.00~~ - 250
700.00

Adrian
1/s 25/04/22
02 Days.

SingDollars : Two Thousand Five Hundred Ninety Only

E. & O.E.

Total S\$: 2,590.00

for PEOPLE'S VEHICLE RECOVERY SERVICE

Computer Generated Invoice.No Signature Required.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 2219.
1/s: 1750