

21/11/22 Asher

Not Authorized
22/4/22
1/5 @ 4100
3 days.

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063/ 67467158 Fax No: 67458520

Tax Reg No : 200006262D

VEHICLE No: SMP 4421D

1PC	BONNET	11	\$1,455.10	X
1PC	BONNET CHROME MOULDING	11	\$345.00	X
2PCS	BONNET HINGES @\$165.00	11	\$330.00	X
1PC	BONNET INSULATOR	11	\$288.90	X
1SET	BONNET INSULATOR CLIPS	11	\$50.00	X
1PC	BONNET RUBBER	11	\$65.00	X
1PC	BONNET LOCK	11	\$245.10	X
1PC	BONNET LOCK CABLE	11	\$188.90	X
1PC	FRONT BUMPER	1288.20	11	\$1,350.10
2PCS	FRONT BUMPER SIDE RETAINERS @\$145.00	11	\$290.00	X
1PC	FRONT BUMPER CENTRE GARNISH	11	\$282.50	X
1PC	FRONT BUMPER LOWER GRILLE	11	\$225.10	X
1PC	FRONT BUMPER SPONGE	Tim	\$156.90	
1PC	FRONT BUMPER REINFORCEMENT	371.20	Surf	\$645.20
1PC	FRONT BUMPER REINFORCEMENT BRACKET O/S	Surf	\$145.00	
1PC	FRONT BUMPER UNDER COVER	11	\$345.90	X
1SET	FRONT BUMPER UNDER COVER CLIPS	11	\$50.00	X
1PC	FRONT BUMPER SPONGE LOWER	11	\$122.80	X
1PC	FRONT GRILLE	645.10	Che	\$855.10
1PC	FRONT GRILLE LOGO	11	\$105.00	X
1PC	FRONT FOG LAMP GARNISH O/S	166.20	Tim	\$283.30
1PC	FRONT FOG LAMP O/S	11	\$450.00	X
1PC	FRONT GRILLE OUTER CHROME	11	\$850.10	X
2PCS	HEADLAMPS @\$3665.10	2584.40	MSA 11	\$7,330.20
1PC	HEADLAMP BALLAST O/S	11	\$485.00	X
2PCS	HEADLAMP LOWER BRACKETS @\$155.10	11	\$310.20	X
1PC	FRONT SUPPORT PANEL ASSY	R	\$1,021.10	X
1PC	FRONT SUPPORT PANEL TOP GARNISH	11	\$388.30	X
1SET	FRONT SUPPORT PANEL TOP GARNISH CLIPS	11	\$45.00	X
1PC	FRONT SUPPORT PANEL SIDE GARNISH O/S	11	\$211.80	X
2PCS	FRONT FENDERS @\$911.20	11	\$1,822.40	X
2PCS	FRONT FENDER INNERSHIELDS @\$311.00	11	\$622.00	X
2PCS	FRONT FENDER 'HYBRID' EMBLEMS @\$150.00	11	\$300.00	X
1PC	AIR CLEANER BOX ASSY	11	\$825.10	X
1PC	AIR CON SUCTION HOSE	11	\$344.50	X
1PC	AIR CON DISCHARGE HOSE	11	\$515.60	X
1PC	AIC CON LIQUID PIPE	11	\$188.90	X
1PC	AIR CON CONDENSER	11	\$1,223.10	X
2PCS	AIR CON SIDE GARNISHS @145.00	11	\$290.00	X
1PC	RADIATOR	11	\$1,961.80	X

257

1PC	RADIATOR FAN ASSY	11	\$1,235.10	X
1PC	RADIATOR 'HYBRID'	11	\$1,421.10	X
1PC	WASHER TANK	11	\$221.00	X
			\$29,887.20	

	S.NETT			
1SET	FRONT BUMPER SENSOR	see	\$280.00	X
1PC	FRONT LICENCE PLATE	see	\$50.00	X
1SET	FRONT BUMPER CLIPS	see	\$50.00	✓
1SET	FRONT FENDER INNER SHIELD CLIPS	11	\$50.00	X
1BOL	RADIATOR COOLANT	1m	\$50.00	X

TO CHECK WIRING	\$100.00	20
TO DISMANTLE & REPLACED FRONT BUMPER SENSOR	\$80.00	50
TO DISMANTLE & REPLACED FRT FENDER GALSS	11	\$100.00 X
TO SPRAY RUST PROOFING	11	\$200.00 X
TO RESET & DIAGNOSE.REPROGRAMME SYSTEM		\$180.00 60
TO REFILL AIR CON GAS	11	\$100.00 X
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$1,200.00	400
TO PUTTYU & SPRAY PAINTING	\$1,200.00	550
TOTAL	\$33,527.20	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2-5357
 252
 7-4017-25
 5.11-50
 2-1080
 5147-75
 202
 4118