



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN: CHAN KIAN CHUAN			Ref: CS/ASM22003762/Eqy3e2 Date: 10/05/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHC 3801A	Veh. Inspected	SG 1145Y
	Policy No.	VFX/P2419138	Coverage (\$)	0.00
	Claim No.	S2M03Z3N	Excess (\$)	0.00
	Assign From	CHAN KIAN CHUAN	Assign Date	22/04/2022
2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ CITARO	c.c	6374
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	WEB62808323130945	Colour	GREEN
	Odometer	278078 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	295/80 R22.5	BRIDGESTONE	5 mm
	L/H Front Tyre	295/80 R22.5	BRIDGESTONE	5 mm
	R/H Rear Tyre	295/80 R22.5 (D)	BRIDGESTONE	5/5 mm
	L/H Rear Tyre	295/80 R22.5 (D)	BRIDGESTONE	5/5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	19/04/2022	Inspection Date	22/04/2022
	Survey held at	3 Yio Chu Kang Crescent road, Singapore 786010		
	Repairer	SBS TRANSIT LTD (Branch)		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		1 Working Days	