

Date: 22/04/2022

Xiao Chen.

TO: Somp Insurance (Singapore) Pte Ltd
50 Raffles Place
#03-03 Singapore Land Tower
Singapore 048623

Our Customer: Phua Wei Loong Ivan
Vehicle No: SJK6496L
Model: Honda Civic 1.8L 5AT
Manufacture Year: 2008 (COE: 28/10/2023)
Date of Accident: 21/04/2022
Total Estimate Repair Days: 7
Total Pages: 2

Attn: Motor Claim Department
Fax: 6221 3147

Re: Repair Estimate For Third Party Claim against XE4381M

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
A.	Spare Parts				
1	Rear bumper side retainer RH <i>3 per</i>	1	\$45.20	\$45.20	✓
2	Rear bumper side retainer LH <i>3 per</i>	1	\$45.20	\$45.20	✓
3	Boot lid <i>Dented</i>	1	\$680.70	\$680.70	✓
4	Boot lid hinge <i>New</i>	2	\$48.60	\$97.20	+
5	Boot lid lock <i>Damaged</i>	1	\$190.50	\$190.50	✓
6	Boot lid lower catch <i>New</i>	1	\$25.30	\$25.30	+
7	Boot lid weatherstrip <i>New</i>	1	\$175.60	\$175.60	+
8	Boot lid "Honda" logo <i>3 per</i>	1	\$55.00	\$55.00	✓
9	Boot lid "Civic" emblem <i>3 per</i>	1	\$58.00	\$58.00	✓
10	Boot lid "Type-R" emblem <i>1</i>	1	\$68.00	\$68.00	✓
11	Boot lid reflector RH <i>3 per</i>	1	\$145.90	\$145.90	+
12	Boot lid reflector LH <i>3 per</i>	1	\$145.90	\$145.90	+
13	Rear number plate lamp <i>New</i>	2	\$121.60	\$243.20	+
14	Tail lamp RH <i>3 per</i>	1	\$286.30	\$286.30	+
15	Tail lamp LH <i>3 per</i>	1	\$286.30	\$286.30	+
16	Tail lamp lower bracket RH <i>3 per</i>	1	\$38.90	\$38.90	+
17	Tail lamp lower bracket LH <i>3 per</i>	1	\$38.90	\$38.90	+
18	Tail lamp panel RH <i>3 per</i>	1	\$65.70	\$65.70	+
19	Tail lamp panel LH <i>3 per</i>	1	\$65.70	\$65.70	+
20	Rear end panel <i>Regr</i>	1	\$428.50	\$428.50	+
21	Rear end panel garnish <i>New</i>	1	\$156.10	\$156.10	+
22	Rear fender inner trim cover RH <i>3 per</i>	1	\$175.20	\$175.20	+
23	Rear fender inner trim cover LH <i>3 per</i>	1	\$175.20	\$175.20	+
24	Spare tyre panel <i>Regr</i>	1	\$992.30	\$992.30	+
25	Spare tyre carrier foam <i>3 per</i>	1	\$312.40	\$312.40	+
26	Spare tyre board <i>3 per</i>	1	\$356.80	\$356.80	+
27	Spare tyre retainer <i>3 per</i>	1	\$70.00	\$70.00	+
30	Exhaust silencer chrome <i>3 per</i>	2	\$94.50	\$189.00	+
31	Exhaust heat shield - rear <i>1</i>	1	\$43.80	\$43.80	+
	Sub Total			\$5,656.80	
	Less 20%			\$1,131.36	
	Sub Total 1			\$4,525.44	
B.	Spare Parts (S/Nett)				
1	Rear number plate w/casing <i>New</i>	1	\$70.00	\$70.00	+
2	Rear bumper <i>Distorted</i>	1	\$1,600.00	\$1,600.00	800.

*Rear bumper spoiler
Distorted*

800 500.

*1142.60
914.08*

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
3	Rear bumper clip <i>new</i>	10	\$5.00	\$50.00	<i>30</i>
4	Rear end panel garnish clip <i>new</i>	8	\$5.00	\$40.00	<i>X</i>
5	Rear fender inner trip clip <i>new</i>	20	\$5.00	\$100.00	<i>X</i>
6	Reverse sensor (set) <i>new</i>	1	\$250.00	\$250.00	<i>30</i>
7	Boot lid spoiler <i>new</i>	1	repair	repair	<i>X</i>
8	Boot lid seal, white <i>new</i>	1	\$120.00	\$120.00	<i>X</i>
Sub Total 2				\$2,230.00	<i>1530</i>
Total Spare Parts				\$6,755.44	
C.	Labour				
1	To check wiring.			\$120.00	<i>30</i>
2	Panel beating charges to remove and replace, to cut and weld, to knock and reshape damaged parts & areas.			\$1,000.00	<i>400</i>
3	Spray painting all affected parts & areas.			\$1,200.00	<i>400</i>
4	To spray anti-rust undercoat.			\$120.00	<i>30</i>
5	To remove and refit rear seats, rear wheelhouse inner garnish, floor carpet & upholstery to facilitate repairs.			\$200.00	<i>30</i>
6	To remove and replace damaged exhaust silencer.			\$250.00	<i>X</i>
Total Labour				\$2,890.00	<i>890</i>
Total Repair Cost				\$9,645.44	

*Adrian King -
4/5 27/04/22 -
04 days.*

Yours faithfully,

Aun Teng
f Premium Carz Services Pte Ltd

Surveyor's Details	
Name	
Contact	
Survey Date	
Recommender	Authorize / Not Authorize
Before Paint	Yes / No

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

*Total: 3334.08
4/5: 2650*