

TP ALG.
Ashes.

SJU7000A. 2011 August.

Mercedes Benz E250 1796cc

WDD2073472F031161

Rees Bumper	Debond	1631	/
		30(SN)	/
Rees Bumper Clips.	new		
Rees Bumper Side Holder x02	new	85x2 = 170.	/
Rees Bumper Lower Garnish.	Disturbed	365	/
Rees Bumper Reinforcement.	Debond	655	/
Rees Bumper Centre Guide.	could	215	/
Rees Bumper Tow Cover.	Missing	35	/
Reverse Sensor x 04.	2 pieces damaged	255x4 = 1020.	510
Reverse Sensor Wire Harness.	HEM	485	x
Rees End Panel	Repair	1023	x
Rees End Panel Top Garnish.	could	275	/
Rees End Panel Top Garnish Clips.	new	20(SN)	/
Rees End Panel Sealant.	HE new	60(SN)	x.
Taillap x 02	could	685x2 = 1350	/
Taillap lower Bracket x 02.	could	65x2 = 130.	/

SJU7000A.

- Bootlid Dented 1835 ✓
- Bootlid Lock Dented 325 ✓
- Bootlid Weatherstripe. ~~ME~~ 298. ✓
- Bootlid Reflector x 02 ~~ME~~ $550 \times 2 = 1100.$ ✓
- Rees Exhaust Pipe. Bent ~~3860.~~ 1700(SN).
- Rees Exhaust Manity x 02 } NY $42 \times 2 = 84.$ ✓
- Rees Exhaust Heat Shield - } her 183. ✓

7794 SN 1770
7014.60

SJU 7000 A.

Panel Beating

Spry Painting.

Wiring.

To remove reuse sensor

To spray tuff coat

To remove upholstery.

To transfer bothid fittings.

To remove exhaust pipe

~~1200~~ 750

~~1000~~ 750

~~85~~ 30

~~100~~ 50

~~150~~ 30

~~150~~ * 50

~~139~~ 60

~~150~~ 120 1840

total: 10624.60

t/s: 8.5K

06 Days.

8500

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: