

Your Ref : SNM22D202713/C01

Date: 06th Oct 2022

Our Ref : CS4/CTI22003776/Nny3e2

M/s China Taiping Insurance (S) Pte Ltd

3 Anson Road #16-00

Springleaf Tower

Singapore 079909

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE GBC 3173A
ACCIDENT ON 20/04/2022**

Instruction was received to inspect the vehicle Reg. No. GBC 3173A. The inspection was conducted on 25/04/2022 at the premises of M/s Hup Soon Lee Motor Service, Block 1018, Yishun Industrial Park A, #01-352, Singapore 768760.

The following vehicle information was recorded:

Registration Number	: GBC 3173A
Make/Model	: Nissan NV200 1.5L MT ABS Airbag 2WD 6DR
Year of Registration	: 2011
Body Colour	: Grey
Chassis Number	: VSKYBAM20U0026614
Engine Capacity	: 1461 cc

The vehicle caught fire. The cause of fire probably due to electrical wiring in engine compartment. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$ 58,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$ 38,435.00)
Nett Liability	<u>S\$ 19,565.00</u> =====

Vehicle Inspected By:



MUHD NAZRIL (NAZ)
Technical Investigator
LL.B. (Hons) London



K.K.LAU
MSc(Eng M), B Eng(Hons), PEng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MII(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.