

KAIZEN MOTORS

KAIZEN MOTORS PTE. LTD.

68 Kaki Bukit Avenue 6, #02-12 Ark@KB, Singapore 417896

UEN: 201502816H

Tel: (+65) 6384 1956

Fax: (+65) 6384 1957

Webpage: <https://www.kaizenmotors.com.sg>



kaizenmotorsingapore



kaizen_motors



kaizenmotors

Not Authorized
new works
26/4/22
2/5 & 4/2021
2 days

Date : 22/04/2022

Vehicle No : SKH5102J

Model : Mercedes E250

Mileage :

Accident Damaged Parts

No	Job Description	Qty	Price / Unit	Amount
1	FRONT L/H HEADLAMP ASSY <i>CNE</i>	1	\$ 3,360.00	\$ 3,360.00
2	FRONT L/H HEADLAMP BRACKET <i>NS</i>	1	\$ 251.00	\$ 251.00
3	FRONT L/H FENDER ASSY <i>nn</i>	1	\$ 1,562.00	\$ 1,562.00
4	FRONT BUMPER <i>De/cu7</i>	1	\$ 1,751.50	\$ 1,751.50
5	FRONT BUMPER LOWER GRILLE <i>nn</i>	1	\$ 376.00	\$ 376.00
6	FRONT BUMPER L/H RETAINER <i>nn</i>	1	\$ 213.30	\$ 213.30
7	FRONT SUPPORT PANEL <i>R</i>	1	\$ 1,982.20	\$ 1,982.20
8	FRONT FOG LAMP GRILLE <i>ns nn</i>	1	\$ 371.00	\$ 371.00
9	FRONT FOG LAMP <i>ns CNE</i>	1	\$ 486.00	\$ 486.00
10	FRONT TOW COVER <i>ns Torn</i>	1	\$ 142.00	\$ 142.00
11	FRONT GRILLE <i>nn</i>	1	\$ 980.00	\$ 980.00
12	FRONT L/H FENDER CLIPS <i>nn</i>	10	\$ 10.00	\$ 100.00
13	FRONT BUMPER CLIPS <i>nn</i>	10	\$ 10.00	\$ 100.00
14	FRONT FENDER INNER GUARD CLIPS <i>nn</i>	10	\$ 10.00	\$ 100.00
15	LABOUR FOR CHECKING ON WIRING		\$ 250.00	\$ 250.00
16	LABOUR FOR DISMANTLING & REPLACING OF ACCIDENT DAMAGED PARTS, INCLUDING WELDING, KNOCKING, REPAIRING, STRAIGHTENING, RESHAPE & ADJUSTMENT OF FRONT L/H HEADLAMP & PARTS		\$ 2,800.00	\$ 2,800.00
17	SPRAYPAINTING & PUTTY OF FRONT BONNET, BUMPER & FENDER		\$ 1,350.00	\$ 1,350.00
18	LABOUR FOR RETROFITTING MOULDING & SEAL		\$ 550.00	\$ 550.00
19	COMPUTER DIAGNOSTIC ON HEADLAMP		\$ 250.00	\$ 250.00

Grand Total \$ 16,975.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

25107.77
10%
2-4596.99
SN-50
L 650
5296.99
202
4237