

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

8 SHENTON WAY #24-01 Date: 19/0 AXA TOWERSINGAPORE 068811 ATTN: KHONG LYNN Code: ASM 1. Policy Particulars :- THIRD PARTY CLAIM	H 5102J)
AXA TOWERSINGAPORE 068811 ATTN: KHONG LYNN Code: ASM 1. Policy Particulars :- THIRD PARTY CLAIM Insured Veh. SMA 8732J Veh. Inspected SKH Policy No. VPA/P2156975 Coverage (\$) 0.00	f 5102J
1. Policy Particulars :- THIRD PARTY CLAIM Insured Veh. SMA 8732J Veh. Inspected SKH Policy No. VPA/P2156975 Coverage (\$) 0.00	H 5102J)
Insured Veh. SMA 8732J Veh. Inspected SKH Policy No. VPA/P2156975 Coverage (\$) 0.00)
Policy No. VPA/P2156975 Coverage (\$) 0.00)
)
Claim No. S2M03Z6D Excess (\$) 0.00	
Assign From KHONG LYNN Assign Date 25/0)4/2022
2. Vehicle Particulars & Condition	
Make & Model MERCEDES BENZ E250 (A) c.c 1796	6
Engine No. HIDDEN Year of Reg. 2012	2
Chassis No. WDD2120472A620005 Colour SILV	/ER
Odometer 196454 KM Steering IN C	ORDER
Brakes IN ORDER Modification STA	NDARD ALLOY RIM
General GOOD	
3. Conditions of Tyres	
Size Make Bala	ance
R/H Front Tyre 245/40 R18 GOODYEAR 6 mr	m
L/H Front Tyre 245/40 R18 GOODYEAR 6 mr	m
R/H Rear Tyre 235/35 R18 GOODYEAR 6 mr	m
L/H Rear Tyre 235/35 R18 GOODYEAR 6 mr	m
4. Description of Damages	
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.	
DAMAGES SEE DETAILS.	
5. General Information	
Accident Date 20/04/2022 Inspection Date 26/0)4/2022
Survey held at KAIZEN MOTORS (ENGINEERING) PTE LTD	
68 KAKI BUKIT AVENUE 6 #02-12 ARK@KB SINGAPORE 417896	
5a. Remarks	
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.	
5b. Estimate Days of Repair	
ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working D	ays