

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0321/2022/JT
DATE : 21-Apr-22
WIP : 20724

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 22/4/22

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Taufikh

5 days exclude 1 Sunday

Johnny Boo 2 Sep 22

OWNER'S NAME : MR YONG CHUN SEK
ADDRESS : BLK 114 DEPOT ROAD
#10-1033
SINGAPORE 100114
TELEPHONE : HP +65 90928989
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210154945
VEHICLE NO : **SKE 1970 L**
MODEL CODE : AUDI A5 SB 2.0 TFSI
MODEL YEAR : 29/12/2021
ENGINE NO : DEM 034228
CHASSIS NO : WAUZZZF52MA062405
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 19-Apr-22
PLACE OF ACCIDENT : HENDERSON ROAD TOWARDS WEST COAST
HIGHWAY AT TRAFFIC JUNCTION BEFORE
TELOK BLANGAH WAY

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKE 1970 L

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SNESOR, HEADLIGHT WASHER ASSY, FORNT PARKING AID AND CAM.	S/N \$	480.00	\$ 480.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	700.00	\$ 350.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND BOTH FRONT HEADLIGHTS. INSPECT LOCK CARRIER FOR DAMAGES. RE-ORGANIZE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,100.00	\$ 1,000.00
4	TO RESPRAY FRONT BUMPER AND BONNET.	\$	1,700.00	\$ 1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$	5,172.00	\$ 3,122.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKE 1970 L

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER	1	\$ 2,493.00	\$	1,994.40
2	SPREADER RIVET	2	\$ 4.00	\$	2.88
3	FRONT BUMPER GRILLE - CENTER	1	\$ 219.00		
4	FRONT BUMPER CLOSING ELEMENT	1	\$ 293.00	\$	234.00
5	RADIATOR GRILLE	1	\$ 1,881.00	\$	1,504.80
6	RADIATOR GRILLE COVER CAP	1	\$ 141.00		
7	RADIATOR GRILLE BRACKET	1	\$ 19.00		
8	RADIATOR GRILLE SECURING PLATE	1	\$ 12.00		
9	FRONT CAMERA	1	\$ 1,261.00		
10	FRONT PARKING AID SENSOR - INNER	2	\$ 530.00		
11	FRONT PARKING AID SENSOR SEAL RING	4	\$ 10.00		
12	FRONT BUMPER FOAM FILLER PIECE	1	\$ 163.00	\$	130.40
13	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 899.00		
14	FRONT BUMPER SUPPORT - LH / RH	2	\$ 64.00	\$	51.04
15	POP RIVET	4	\$ 4.00	\$	2.88
16	FRONT BUMPER LOCK CARRIER BRACKET	1	\$ 154.00	\$	122.80
17	FRONT BUMPER TOP COVER	1	\$ 143.00	\$	114.00
18	CAUTION STICKER	1	\$ 16.00	\$	12.40
19	AIR COND STICKER	1	\$ 9.00	\$	6.64
20	BONNET	1	\$ 3,491.00	\$	2,792.80
SUB TOTAL SPARE PARTS		:	\$ 11,806.00	\$	6,969.04

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKE 1970 L

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		<i>\$</i>	<i>6,969.04</i>
21	BONNET ATTACHMENT PARTS	1	\$ 128.00		
22	BONNET IMPACT PROTECTION - CENTER / LH / RH	3	\$ 93.00	<i>\$</i>	<i>73.20</i>
23	BONNET STRIKER - LH / RH	2	\$ 112.00		
24	BONNET LOCK	2	\$ 455.00		
25	HEADLIGHT MATRIX BEAM - LH / RH	2	\$ 16,344.00	<i>\$</i>	<i>6,537.60</i>
26	RADIATOR AIR GUIDE INNER / OUTER - LH	2	\$ 55.00	<i>\$</i>	<i>14.64</i>
27	RADIATOR AIR GUIDE INNER / OUTER - RH	2	\$ 55.00	<i>\$</i>	<i>14.64</i>
28	FRONT NO PLATE	S/N	\$ 60.00	<i>\$</i>	<i>60.00</i>
29	Added parts - see attached		\$ 64.00	<i>\$</i>	<i>50.56</i>
30	SUNDRIES		\$ 400.00	<i>\$</i>	<i>27.04</i>
TOTAL SPARE PARTS			\$ 29,572.00	<i>\$</i>	<i>13,746.72</i>
TOTAL LABOUR CHARGES			\$ 5,172.00	<i>\$</i>	<i>3,122.00</i>
GRAND TOTAL			\$ 34,744.00	<i>\$</i>	<i>16,868.72</i>

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 b/l/27/07/22



55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183
Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate-1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0321/2022/JT 28-Jun-22 CHANG 1 of 1 SKE 1970 L AUDI A5 SB 2.0 TFSI
Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	BONNET BOWDEN CABLE - CENTER 1	\$ 64.00	\$ 50.56
	GRAND TOTAL	\$ 64.00	\$ 50.56

For Premium Automobiles Pte Ltd

Authorised Signature



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT