

ASS. REC. BY: Marcus

REF:

CS/FC/22003782/U4y3

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMD 687E
at Workshop m/s KT Garage

Insured: SBS39257

Policy No.

Claims No. D22001003MFBP

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$69k.

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted: 119k Vehicle: IN / OUT
27A830640

Veh No: SMD 687E Yr Regn: 30/08/18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (A/

Make: KIA Cerato EX c.c 1591

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 80 11-2 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: KN AF3416MKS013510

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16
R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or champion

Front

Rear

R/Bal. 7 mm R/Bal. 7 mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. 03/04/22 D.O.I. 25/4/22

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction Sep 10k.

28/4/22 L/S \$2050 informed A/I Keary (red \$5586.06, 73%)

Date/Time, File Pass to?

☐

: Preli. Report

1) 28/4/22

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

___ S + RS, ___ SI

) Photos

) Others

Report Format : TP

Lump Sum / I.B.I. (\$) 2050)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

TOTAL



KT GARAGE PTE LTD UEN: 201906115R
Auto Bay@ Kaki Bukit Entrance A
BLK 1 Kaki Bukit Ave 6 #01-04 Singapore 417883

Date :

TO: First Capital Insurance Ltd
6 Raffles Quay,
Singapore 048580

Total Pages :

Our Customer : Soh Puay Guan

Vehicle No : **SMD6857E**

Model : Kia Cerato 1.6 (A)EX

Manufacture Year :

Date of Accident : 3/4/2022

Total Estimate Repair Days :

Attn : Motor Claim Department

Email : motor_claims@msfirstcapital.com.sg

Re: Repair Estimate For Third Party Claim against : SBS3975T

Not Authorized
25/4/22
e/s #2050/
The No. of days
3 days

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
A.	Spare Parts				
1	Rear Bumper	1	\$688.00	\$688.00	DO/AE ✓
2	Rear Bumper Clip	13	\$3.50	\$169.40	161 ✓
3	Rear Bumper Diffusion	1	\$197.00	\$197.00	171 ✓
4	Rear Bumper Signal Lamp	2	\$187.00	\$374.00	171 X
5	Rear Bumper Signal Lamp Trim	2	\$28.00	\$56.00	171 ✓
6	Rear Bumper Reinforcement	1	\$313.00	\$313.00	171 ✓
7	Rear Bumper Foam	1			171 X
8	Rear Bumper Side Retainer	2	\$28.00	\$56.00	171 ✓
9	Boot	1	\$1,297.00	\$1,297.00	171 X
10	Bootlid Lock	1	\$122.00	\$122.00	171 X
11	Bootlid Emblem	1	\$32.00	\$32.00	171 ✓
12	Bootlid Ceranto Lettering	1	\$28.00	\$28.00	171 ✓
13	Bootlid CFC Emblem	1			171 X
14	Bootlid chrome Moulding	1			171 X
15	Bootlid Reflector (RH/LH)	2	\$608.00	\$1,216.00	171 X
16	Bootlid Reflector Centre	1	\$690.00	\$690.00	171 X
17	Bootlid Keyless Sensor	1	\$95.00	\$95.00	171 X
18	Bootlid Weatherstrip	1	\$100.00	\$100.00	171 X
19	End Panel	1	\$324.00	\$324.00	171 X
20	End panel Top Garnish	1	\$66.00	\$66.00	171 X
Sub Total				\$5,823.40	
Less 10%				\$582.34	
Sub Total 1				\$5,241.06	
A.	Spare Parts (S/NETT)				
1	Rear Paarking Sensor			\$120.00	500 ✓
2	Rear Number Plate With Casing			\$25.00	171 X
3					
4					
Sub Total 2				\$145.00	
B.	Labour				
1	To knock and straighten necessary portion. To remove and renew damaged panel. To adjust and reagline the same.			\$800.00	450
2	To rust proof all affected areas			\$80.00	171 X
3	To install reverse sensor			\$120.00	50
4	To check wiring and all lighting			\$120.00	20
5	To Remove Upholstery			\$80.00	80



KT GARAGE PTE LTD UEN: 201906115R

Auto Bay@ Kaki Bukit Entrance A

BLK 1 Kaki Bukit Ave 6 #01-04 Singapore 417883

6	Labour to transfer Boot mechanic parts	\$150.00	max
7	Spray Paint	\$900.00	600
8			
Total Labour		\$2,250.00	
Total Repair Cost		\$7,636.06	
* The above quoted are exclusive of GST.			

Yours faithfully,

KAI
f KT Garage Pte Ltd

Surveyor's Details	
Name	Mercury
Contact	90096608
Survey Date	15-04-22
Recommend	Authorize / Not Authorize
Before Paint	Yes / No
Signature	

P-1415.50
102
P-1273.95
S-N-120
L 1200
2593.55

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

202
2075