

**COMFORTDELGRO  
ENGINEERING**

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508669  
Fax: 6546 8156

Our Job Ref No : 305513261  
Date : 27 04 22

**FINALIZATION FORM**

To : LKK  
Attn : THEVAN  
Vehicle Reg No. : SHA4213B

Fax :

Date of Accident : 20.04.22

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC --- SMJ6933L
2. The finalized amount shall be:
  - (a) Spare Parts after List discount \_\_\_\_\_
  - (b) Labour Charges (include advertisement stickers etc, if any) \_\_\_\_\_
  - Total for Part-By-Part Repair Cost** \_\_\_\_\_
  - (c) Lumpsum Repair (if applicable) \_\_\_\_\_
  - Total for Lumpsum repair cost after Less: 20% \$3,000.00
  - Final Lumpsum Repair cost** \$3,000.00

3. Estimated normal period for repairs: 3 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature :   
Name : LIM J  
Tel : 82148298  
Fax : 85468156

Signature :   
Name : THEVAN  
Date : 28/4/22

**For Official Use Only**

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Repair Parts P/L		YES		
2. Labour Charges		N		
3. Spares		"		
4. LTA Service Fee	<u>\$7,491/2.50</u>			
5. Material Fees (on behalf of driver, if applicable)				
6. Other				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Effective Date: 1 Nov 2020

SAS-KIV

LKK -

DATE: 21.04.22

MODEL: Hyundai i40

INSURANCE: NTUC (LKS)

VEHICLE NO.: SHA4213B

MVA: LIM T S

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Front Door RH	1		\$ 2,707.70 KY
	Rear Door RH	1		\$ 2,201.10 NT
	Rocker Panel Garnish RH	1		\$ 732.80 KV
	Rear Wheel Cap RH	1		\$ 217.20 SCR
	<b>SUB TOTAL</b>			\$ 5,858.80
	<b>LESS 20%</b>			\$ 1,171.76
	<b>DISCOUNTED TOTAL</b>			\$ 4,687.04
	Front Door ComfortDelGro RH	1		\$ 75.00 HCE
	Rear Door APPS RH	1		\$ 80.00 HCE
	<b>SUB S/NETT</b>			\$ 155.00
	<b>LESS 10%</b>			\$ 15.50
	<b>S/NETT TOTAL</b>			\$ 139.50
	<b>SPARE PARTS TOTAL</b>			\$ 4,826.54
	<u>Labour Charge</u>			
	Panel Beating - Rear Fender RH etc			\$ 800.00 560
	Spray Painting Charge - Rear Bumper etc			\$ 1,200.00 1000
	Transfer Of Doors	2	\$ 120.00	\$ 240.00 120
	Wheel Alignment			\$ 120.00 XNW
	<b>TOTAL LABOUR</b>			\$ 2,360.00
	<b>ESTIMATE TOTAL</b>			\$ 7,186.54

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Thivan  
82235769  
21/4/22 1600  
L/S 3clays wp

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: