



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
KELVIN CHIA PARTNERSHIP 6 TEMASEK BOULEVARD 29TH FLOOR SUNTEC TOWER FOUR SINGAPORE 038986			Ref: CS/LAW22003788/Dvy3e2	
			Date: 17/05/2022	
			Code: L041	
<b>1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)</b>				
	Insured Veh.	FBL 409T	Veh. Inspected	SKN 3080U
	Policy No.		Coverage (\$)	0.00
	Claim No.	2021000598.Sompo(mpd)	Excess (\$)	0.00
	Assign From	VITHYANAGAN PANDIAN	Assign Date	07/04/2022
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	TOYOTA ALPHARD	c.c	2362
	Engine No.	HIDDEN	Year of Reg.	2007
	Chassis No.	ANH100184299	Colour	GREY
	Odometer	590108 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	215/55 R17	MICHELIN	5 mm
	L/H Front Tyre	215/55 R17	MICHELIN	5 mm
	R/H Rear Tyre	215/55 R17	MICHELIN	5 mm
	L/H Rear Tyre	215/55 R17	MICHELIN	5 mm
<b>4. Description of Damages</b>				
	THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	30/10/2019	Inspection Date	28/04/2022
	Survey held at	50 Serangoon North Avenue 4 #02-19 First Center Bu		
	Repairer	D'S GRAFFITI CONCEPTS PTE LTD		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	