

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22003790/UPA3Q2**Date:** 12/10/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100484676
Claimant Vehicle No :	FZ665Z	Insured Vehicle No :	SLG4670K
Date of Loss:	21/04/2022	Nature of Claim:	TP
		Claim No:	6509897636SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FZ665Z	Engine No:	21CD010381
Make & Model:	YAMAHA FZ16, 153cc (M)	Chassis No:	ME121C0D8C2010388
Reg. Date:	15/09/2012 (Man. Year: 2012)	Odometer:	99999 km
Colour:	Red		
Engine Capacity:	153 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	100/80 -17	Rear Tyre Size:	150/60 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,112.00	1,067.40	2,044.60	65.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	560.00	485.00	75.00	13.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,672.00	1,552.40	2,119.60	57.72
Approved Total (Overridden) (S\$)		1,200.00		
(S\$)	3,672.00	1,200.00	2,472.00	67.32
+ GST 7.00/7.00% (S\$)	257.04	84.00	173.04	67.32
Nett Amount (S\$)	3,929.04	1,284.00	2,645.04	67.32
+ Loss of Use (3.0 x S\$20.00/day) (S\$)		60.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,346.00		

INSPECTION

Date of Assignment:	25/04/2022	
Date Inspected:	25/04/2022	Inspected At: Ban Hock Hin Co. Pte Ltd (HQ) No. 6 Defu Lane 4 Singapore 539410
Estimated Period of Repair:	3.0 days	

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*ALIGNMENT BODY FRAME REAR	Not Necessary	280.00 F	*- FL
2	1		*BAR FOOTREST FRONT RH	Cut	14.00 F	*14.00 FL
3	1		*BAR HANDLE	Bent	42.00 F	*42.00 FL
4	1		*BELLYPAN (AFTERMARKET)	Cracked	154.00 F	*154.00 FL
5	1		*BOLT FOOTREST REAR	Bent	6.00 F	*6.00 FL
6	1		*BRACKET BOX REAR (KUCAY)	Cracked	210.00 F	*210.00 FL
7	1		*BRACKET UNDER FORK	Not Necessary	235.00 F	*- FL
8	1		*BRACKET VISOR	Repair	17.00 F	*- FL
9	1		*CABLE THROTTLE 2	Cut	30.00 F	*30.00 FL
10	1		*CAP END MUFFLER (BLACK)	Cut	30.00 F	*30.00 FL
11	1		*CAP RESERVOIR	Cut	14.00 F	*14.00 FL
12	1		*COVER TANK RH (RED)	Repair	154.00 F	*- FL
13	1		*FOOTREST REAR 2	Cut	14.00 F	*14.00 FL
14	1		*FORK FRONT ASSY LH	Serviceable	510.00 F	*- FL
15	1		*FORK FRONT ASSY RH (BLACK)	Serviceable	510.00 F	*- FL
16	1		*GRIP HANDLE (MONSTER)	Torn	63.00 F	*63.00 FL
17	1		*GRIP HANDLE RH ASSY	Cut	16.00 F	*16.00 FL
18	1		*HEADLAMP ASSY	Cracked	155.00 F	*155.00 FL
19	1		*KICK STATER ASSY	Repair	42.00 F	*- FL
20	1		*LAMP SIGNAL FRONT RH	Cut	16.00 F	*16.00 FL
21	1		*LEVER BRAKE SET (AFTERMARKET)	Cut	84.00 F	*84.00 FL
22	1		*MIRROR AFTERMARKET	Broken	70.00 F	*70.00 FL
23	1		*MUDGUARD FRONT (RED)	Repair	54.00 F	*- FL
24	1		*PROTECTOR MUFFLER (SILVER)	Cut	44.00 F	*44.00 FL
25	1		*RUBBER FOOTREST FRONT	Torn	9.00 F	*9.00 FL
26	1		*STAY HEADLIGHT	Serviceable	56.00 F	*- FL
27	1		*SET STEERING CONE	Not Necessary	68.00 F	*- FL
28	1		*BOX REAR (GIVI) E450N BLACK W/O STOP LIGHT	Cut	215.00 F	*215.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	3,112.00	1,186.00
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	118.60
Total Parts (\$)	3,112.00	1,067.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TRANSPORT CHARGES	New	56.00	35.00
2	LABOUR	New	504.00	450.00
Gross Labour Cost (S\$)			560.00	485.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >