



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATION | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

AIG ASIA PACIFIC INSURANCE PTE LTD
CHARTIS BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120
ATTN: MOTOR CLAIMS DEPT

NO. : 40517

- Rev. 1

DATE : 25/04/2022
CLAIM NO. : 11916
POLICY NO. : MC/00686706/02

FROM : RAYMOND

VEHICLE NO. : FZ0665Z
MAKE/MODEL : YAM / FZ16

*not Allowed
2/5/22
3 days
25/4/22
Take 2/5/22*

(Page 1 of 3)

S/N	Description	Action	Qty	Unit Price	Amount
1	ALIGNMENT BODY FRAME REAR - (REPORTED BY MECHANIC)	Repair	1.00	\$280.00	280.00 X
2	BAR FOOTREST FRONT RH P/N: 40315 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$14.00	14.00
3	BAR HANDLE P/N: 44886 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$42.00	42.00
4	BELLYPAN (AFTERMARKET) P/N: 59851 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$154.00	154.00
5	BOLT FOOTREST REAR P/N: 44888 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$6.00	6.00
6	BRACKET BOX REAR (KUCAY) P/N: 46429 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$210.00	210.00
7	BRACKET UNDER FORK P/N: 52944 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$235.00	235.00 X
8	BRACKET VISOR - (REPORTED BY MECHANIC)	REPLACE	1.00	\$17.00	17.00 X
9	CABLE THROTTLE 2 P/N: 50302 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$30.00	30.00

*40517 *

biSAFE₃



Address: No.6, Defu Lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
Fax: (Main) + 65 6281 2830, (Spare Parts) + 65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) + 65 6281 6759

CERT NO.: 2002-1-0383
ISO 9001 : 2015

S/N	Description	Action	Qty	Unit Price	Amount
10	CAP END MUFFLER (BLACK) P/N: 43631 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$30.00	CU 30.00
11	CAP RESERVOIR P/N: 51562 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$14.00	CU 14.00
12	COVER TANK RH (RED) P/N: 63578 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$154.00	R 154.00 X
13	FOOTREST REAR 2 P/N: 45127 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$14.00	CU 14.00
14	FORK FRONT ASSY LH P/N: 50469 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$510.00	SR 510.00 X
15	FORK FRONT ASSY RH (BLACK) P/N: 59801 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$510.00	SR 510.00 X
16	GRIP HANDLE (MONSTER) P/N: 64920 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$63.00	TOIN 63.00
17	GRIP HANDLE RH ASSY P/N: 44984 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$16.00	CU 16.00
18	HEADLAMP ASSY P/N: 41632 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$155.00	CNE 155.00
19	KICK STATER ASSY - (REPORTED BY MECHANIC)	REPLACE	1.00	\$42.00	R 42.00 X
20	LABOUR P/N: 06766	Supply/Install	8.00	\$63.00	450 504.00
21	LAMP SIGNAL FRONT RH P/N: 45130 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$16.00	CU 16.00
22	LEVER BRAKE SET (AFTERMARKET) P/N: 69509 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$84.00	CU 84.00
23	MIRROR AFTERMARKET - (REPORTED BY MECHANIC)	REPLACE	1.00	\$70.00	SR 70.00
24	MUDGUARD FRONT (RED) P/N: 55147 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$54.00	R 54.00 X
25	PROTECTOR MUFFLER (SILVER) P/N: 40320 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$44.00	CU 44.00

*40517 *

bizSAFE₃

S/N	Description	Action	Qty	Unit Price	Amount
26	RUBBER FOOTREST FRONT P/N: 40321 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$9.00	7011 9.00
27	STAY HEADLIGHT P/N: 52257 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$56.00	506 56.00 X
28	STEERING CONE SET P/N: 33765 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$68.00	17 68.00 X
29	TRANSPORT CHARGES P/N: 07169	X	1.00	\$56.00	35 56.00
30	BOX REAR (GIVI) E450N BLACK W/O STOP LIGHT P/N: 27220	Replace	1.00	\$215.00	647 215.00 ✓
SUB TOTAL					\$3,672.00
GST @ 7 %					\$257.04
GRAND TOTAL (SGD)					\$3,929.04

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of
BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

p. 1186
102
1067.4
480
1517.4

*40517 *

bizSAFE₃

