

1. *Journal of the American Medical Association*, 1997; 278: 1019-1024.

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 25-Apr-22

INSURANCE: China Teeping

MODEL: HYUNDAI IONIC

VEHICLE NO.: SHC 1012Z

Description	Qty	List Price	Amount
Bonnet <i>Scratch</i>	1	\$ 2,253.80	\$ 2,253.80
Bonnet Moulding <i>HH</i>	1	\$ 41.40	\$ 41.40
Radiator Grille <i>cut</i>	1	\$ 1,409.10	\$ 1,409.10
Flap Assy Active Air Upper, (LH) <i>HH</i>	1	\$ 824.60	\$ 824.60
Front Bumper Cover <i>broken/cut</i>	1	\$ 481.10	\$ 481.10
Front bumper top cover <i>HH</i>	1	\$ 476.30	\$ 476.30
Front Bumper Sponge <i>broken</i>	1	\$ 186.90	\$ 186.90
Front Bumper Reinforcement <i>at Scratch</i>	1	\$ 1,136.70	\$ 1,136.70
Front Bumper Reinforcement ABSORBER (LH) <i>HH</i>	1	\$ 186.50	\$ 186.50
Front Bumper Towing Cover <i>HH</i>	1	\$ 29.00	\$ 29.00
Front Bumper Moulding Centre Upper <i>HH cut</i>	1	\$ 368.50	\$ 368.50
Front Bumper Moulding <i>HH</i>	1	\$ 93.60	\$ 93.60
Front Bumper Bracket Top (LH) <i>HH</i>	1	\$ 35.00	\$ 35.00
Front Bumper Bracket (LH) <i>broken</i>	1	\$ 28.00	\$ 28.00
Front Bumper Retainer Mounting (LH) <i>HH</i>	1	\$ 65.30	\$ 65.30
Front Bumper Clips 10 pcs <i>HH</i>	1	\$ 25.00	\$ 25.00
Front Bumper Grille (LH) <i>cut</i>	1	\$ 186.90	\$ 186.90
Front bumper air duct (LH) <i>crack mounting</i>	1	\$ 153.80	\$ 153.80
Day Light LH <i>missing crack</i>	1	\$ 642.50	\$ 642.50
Day Light Wire, <i>HH</i>	1	\$ 585.50	\$ 585.50
BUZZER ASSY - PIEZO (LH) <i>HH</i>	1	\$ 388.00	\$ 388.00
Headlamp Support Panel Assy <i>crack</i>	1	\$ 1,139.30	\$ 1,139.30
Headlamp(LH) <i>broken</i>	1	\$ 3,987.30	\$ 3,987.30
Radiator Inverter <i>HH</i>	1	\$ 884.80	\$ 884.80
Radiator <i>HH</i>	1	\$ 710.50	\$ 710.50
Radiator Air Guard (LH) <i>HH</i>	1	\$ 76.40	\$ 76.40
Radiator Air Guard, Upr (LH) <i>HH</i>	1	\$ 127.50	\$ 127.50
Front Fender(LH) <i>Scratch</i>	1	\$ 490.70	\$ 490.70
Front Fender Shield (LH) <i>HH turn</i>	1	\$ 164.70	\$ 164.70
Aircon Condenser <i>HH</i>	1	\$ 663.60	\$ 663.60
Front Wheel Rim (LH) <i>HH</i>	1	\$ 1,124.20	\$ 1,124.20
Front Wheel Hub assy (LH) <i>HH</i>	1	\$ 678.50	\$ 678.50
Front Shock Absorber(Assy)(LH) <i>HH</i>	1	\$ 372.50	\$ 372.50
Front Shock Absorber Mounting (LH) <i>HH</i>	1	\$ 372.50	\$ 372.50
Front Drive Shaft (LH) <i>HH</i>	1	\$ 1,136.70	\$ 1,136.70
Rack & Pinion Assy <i>HH</i>	1	\$ 2,387.40	\$ 2,387.40
STG Tie Rod <i>HH</i>	1	\$ 125.60	\$ 125.60
STG Tie End <i>HH</i>	1	\$ 94.70	\$ 94.70
Stabilizer Bar <i>HH</i>	1	\$ 326.80	\$ 326.80
Stabilizer Bar Link <i>HH</i>	1	\$ 92.10	\$ 92.10
Front Suspension Lower Arm (LH) <i>HH</i>	1	\$ 596.80	\$ 596.80
Knuckle Arm (LH) <i>HH</i>	1	\$ 663.60	\$ 663.60

✓

X

✓

X

✓

X

✓

✓

X

X

✓

X

X

✓

X

✓

✓

✓

✓

X

X

✓

✓ 2110-30

X

X

X

X

✓

✓

X

X

X

X

X

X

X

X

X

X

X

X

X

SUB TOTAL						\$ 25,813.70
LESS 20%						\$ 5,162.74
DISCOUNTED TOTAL						\$ 20,650.96
COOLANT HH	List	SN	1	\$	45.00	\$ 45.00 X
Emblem-Blue Drive (LH) HHC	List	SN	1	\$	26.60	\$ 26.60 ✓ List
Front Tyre(LH) HH		SN	1	\$	216.00	\$ 216.00 X
SUB TOTAL						\$ 287.60
Labour Charge						
Panel Beating			1	\$	1,600.00	\$1,600.00 600/-
Spray Painting Charge			1	\$	1,400.00	\$1,400.00 600/-
Wiring Charge			1	\$	100.00	\$100.00 30/-
Tuff Kote			1	\$	100.00	\$100.00 40/-
Towing Charge			1	\$	80.00	\$80.00 HH
Four Wheel Alignment			1	\$	120.00	\$120.00 HH
Remove/Refix Undercarriage (Frt)			1	\$	400.00	\$400.00 HH
Re-set Frt ABS System			1	\$	200.00	\$200.00 HH 1270.00
Remove/Refix Radiator			1	\$	90.00	\$90.00 HH
Remove/Refix Aircon & Refill Gas			1	\$	130.00	\$130.00 HH
Diagnostic & Resetting To Erase Fault Code			1	\$	550.00	\$550.00 HH
TOTAL LABOUR						\$4,770.00
ESTIMATE TOTAL						\$ 25,708.56
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance						

10,803.90
8,643.12 =

✓ List

600/-

600/-

30/-

40/-

HH

HH

HH

HH

HH

HH

HH

HH

25/04/2022 @ 1700hrs

Not Andrew

2/sum

Tyuan

5
4 days.

LKK Ando



9,913.12

4/5 8,900/-

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: