

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

India International Insurance Pte Ltd
64 Cecil Street, #04-00 IOB Building
Singapore 049711

Our File No: CS/III22003795/GVY3E2

Date: 18/05/2022

REFERENCE

Insured/Claimant: ComfortDelGro Driving Centre Pte Ltd Policy No: D20MFL0000637_02
Date of Loss: 06/04/2022 Nature of Claim: OD Claim No: MFL2022D0002089

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBN7901G**
Make & Model: YAMAHA YBR125, 124cc (M) Engine No: E3F5E045266
Reg. Date: 10/12/2018 (Man. Year: 2018) Chassis No: LBPRI1022J0010566
Colour: Red Odometer: 81781 km
Engine Capacity: 124 cc
Market Value/New Car Price: S\$7,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 2.75-18 Rear Tyre Size: 2.75-18
Front Left Side: Timsun 5 mm Rear Left Side: Timsun 5 mm
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,600.87	1,600.87	0.00	0.00
Miscellaneous Items	1,060.00	1,060.00	0.00	0.00
Labour	280.00	280.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,940.87	2,940.87	0.00	0.00
+ GST 7.00/7.00% (S\$)	205.86	205.86	0.00	0.00
Nett Amount (S\$)	3,146.73	3,146.73	0.00	0.00

INSPECTION

Date of Assignment: 25/04/2022
Date Inspected: 25/04/2022 Inspected At: 178 Paya Lebar Road
Estimated Period of Repair: 3.0 days Repairer: Kang Car Repairers Pte Ltd (HQ)

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

INSURED WITHDRAW OD CLAIM
(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 18 May 2022)	
Parts:	N/A	YAMAHA YBR125 124cc (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBN7901G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*MUFFLER ASSY	Cut	1,300.00 FL	*1,300.00 FL
2	1		*FRONT FENDER ASSY	Cut	65.00 FL	*65.00 FL
3	1		*FUEL TANK ASSY	Dented	340.00 FL	*340.00 FL
4	1		*GASKET	Necessary	5.00 FL	*5.00 FL
5	1		*DAMPER, SIDE COVER	Necessary	2.00 FL	*2.00 FL
6	1		*CAST WHEEL FRONT	Bent	275.00 FL	*275.00 FL
7	1		*OIL SEAL	Necessary	1.50 FL	*1.50 FL
8	1		*VAVLE, RIM	Necessary	7.00 FL	*7.00 FL
9	1		*AXLE WHEEL	Necessary	11.00 FL	*11.00 FL
10	4		*BOLT, HEX	Necessary	14.00 FL	*14.00 FL
11	1		*HANDLE BAR	Bent	32.00 FL	*32.00 FL
12	1		*GRIP ASSY	Cut	12.00 FL	*12.00 FL
13	1		*GRIP	Cut	2.00 FL	*2.00 FL
14	1		*REAR VIEW MIRROR (LHS)	Distorted	20.00 FL	*20.00 FL
15	1		*REAR VIEW MIRROR (RHS)	Distorted	20.00 FL	*20.00 FL
16	1		*LEVER 2	Cut	12.50 FL	*12.50 FL
17	1		*COVER, FOOTREST	Cut	7.00 FL	*7.00 FL
18	1		*LEVER 1	Cut	8.50 FL	*8.50 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	2,134.50	2,134.50
- List Item Discount on L Items 25.00/25.00% (S\$)	533.63	533.63
Total Parts (S\$)	1,600.87	1,600.87

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	2	BEARING (NECESSARY)	10.00	10.00
2	1	FRONT LOWER CRASHBAR (CUT)	400.00	400.00
3	1	FRONT UPPER CRASHBAR (CUT)	400.00	400.00
4	1	RH CRASHBAR (CUT)	250.00	250.00
Sub Total (\$\$)			1,060.00	1,060.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO REPLACE ACCIDENT PARTS	New	280.00	280.00
Gross Labour Cost (\$\$)			280.00	280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >