

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29
 Kaki Bukit Autohub, Singapore 417921
 Tel No. : 67461515 / 67471787 Fax No. : 67485015
 Website : www.successunited.com.sg
 Buss. Reg. No. : GST No. 200402570G

AIG Asia Pacific Insurance Pte Ltd
 AIG Building
 78 Shenton Way, #07-16
 Singapore 079120
 Attention : Motor Claim Department
 Contact : 64191053 Fax No. : 68357416

Ashes

Estimate : TP22-040

Date : 14/04/2022
 Vehicle Num. : SMQ200X
 Make/Model : Toyota Estima-2008
 Chassis/Eng# : ACR500072554/2AZC403370
 Accident Date : 04/04/2022
 Claim No. :
 Reference :
 Policy No. : (04/07/2022)

S/N	Quantity	Particular	Unit Price	Amount SS
-----	----------	------------	------------	-----------

1.	1 pc	LIST ITEMS : Frt Bumper Assy <i>rehd</i>		982.10 ✓
2.	5 pcs	Frt Bumper Clips <i>su</i>		28.90 ✓
3.	1 pc	Frt Bumper Side Holder RH <i>su</i>		151.20 ✓ 78
4.	1 pc	Frt Fender Inner Liner RH <i>fora</i>		285.60 ✓
5.	1 pc	Frt Bumper Foglamp RH <i>new</i>		249.80 ✓

1374.60
1030.95

List TotalSS :
 25.00% Discount SS :

1,697.60
 424.40

 1,273.20

LABOUR :
 To remove, repair and replaced damaged bodyparts,
 realign bodyworks & where consistent to the accident
 .
 To putty and respray painting on affected area.

700

500.00 *300*

 800.00 *400*

 1,300.00

Labour Total SS :

Total SS : 2,573.20
 =====

AD
 SUCCESS UNITED PTE LTD

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Admin L
2/s 22/04/22
03 Days
total: 1730.95
4/s: 1350