

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22003801/VTY3Q2**Date:** 30/05/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00204262100		
Claimant Vehicle No :	SMK3913J	Insured Vehicle No :	SLK2642J		
Date of Loss:	19/04/2022	Nature of Claim:	TP	Claim No:	SNM22D202720/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMK3913J		
Make & Model:	MAZDA 5, 2.0 (A)	Engine No:	PE10402718
Reg. Date:	16/02/2017 (Man. Year: 2016)	Chassis No:	JM6CW1071G0124770
Colour:	White	Odometer:	72447 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,926.00	2,547.20	1,378.80	35.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,800.00	830.00	970.00	53.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	5,726.00	3,377.20	2,348.80	41.02
Approved Total (Overridden) (\$\$)		2,700.00		
(\$\$)	5,726.00	2,700.00	3,026.00	52.85
+ GST 7.00/7.00% (\$\$)	400.82	189.00	211.82	52.85
Nett Amount (\$\$)	6,126.82	2,889.00	3,237.82	52.85

INSPECTION

Date of Assignment:	28/04/2022		
Date Inspected:	27/04/2022	Inspected At:	Dickson Auto Care Centre Pte Ltd (HQ) 29 Ubi Road 4, Dickson Auto Centre Singapore 408619
Estimated Period of Repair:	5.0 days		

Adjuster: Thevan Thomas Karthikesavan**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 May 2022)
Parts:	M1-MPV	MAZDA 5 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMK3913J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE	Dented	1,638.00 F	*1,638.00 FL
2	1		*TAIL GATE LOGO	Necessary	45.00 F	*45.00 FL
3	1		*TAIL GATE MAZDA LOGO	Necessary	46.00 F	*46.00 FL
4	1		*TAIL GATE 5 LOGO	Necessary	37.00 F	*37.00 FL
5	1		*TAIL GATE SKYACTIVE LOGO	Necessary	80.00 F	*80.00 FL
6	1		*REAR BUMPER	Cut	962.00 F	*962.00 FL
7	10		*REAR BUMPER CLIPS	Necessary	100.00 F	*30.00 FL
8	2		*REAR BUMPER SIDE RETAINER LH & RH	Necessary	96.00 F	*96.00 FL
9	1		*REAR BUMPER REINFORCEMENT	Repair	156.00 F	*- FL
10	1		*REAR END PANEL	Repair	516.00 F	*- FL
11	1		*REVERSE SENSOR	Cut	250.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	3,926.00	3,134.00
- List Item Discount on L Items 0.00/20.00% (\$)	0.00	586.80

Total Parts (\$)	3,926.00	2,547.20
-------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REPLACE REVERSE SENSOR AND WIRING	New	200.00	30.00
2	TO PROVIDE SKILL LABOUR TO REMOVE ALL DAMAGED PARTS & PANELS ,CUT & WELD IN PLACE NEW PARTS & PANELS WITH FULL ALIGNMENT	New	800.00	400.00
3	TO PROVIDE SKILL LABOUR & MATERIAL TO PREPARE & PAINT ALL NEW PARTS & PANELS	New	800.00	400.00
Gross Labour Cost (\$\$)			1,800.00	830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >