



DICKSON GROUP
Your Trusted Automotive Solutionist

DICKSON AUTO CARE CENTRE PTE LTD
29 UBI ROAD 4, DICKSON AUTO CENTRE
SINGAPORE 408619
TEL: 6668 1122 | FAX: 6668 1123

QUOTATION

QUOTATION FOR

NAME: China Taiping Insurance (Singapore) Pte Ltd
COMPANY NAME: China Taiping Insurance (Singapore) Pte Ltd
STREET ADDRESS: 3 Anson Road, #16-00 Springleaf Tower
POSTAL CODE: Singapore 079909
PHONE: 6389 6111

DATE: 22/4/2022
REF: SM3913J
VEHICLE NO.: SM3913J
MAKE: MAZDA
MODEL: 5
PREPARED BY: POON

S/N	DESCRIPTION	QTY	UOM	UNIT PRICE	AMOUNT BEFORE DISCOUNT	DISC	AMOUNT
	LABOUR						
1	TO REMOVE & REPLACE REVERSE SENSOR AND WIRING	1		\$200.00	\$ 200.00	30	\$ 200.00
2	TO PROVIDE SKILL LABOUR TO REMOVE ALL DAMAGED PARTS & PANELS, CUT & WELD IN PLACE NEW PARTS & PANELS WITH FULL ALIGNMENT	1		\$800.00	\$ 800.00	400	\$ 800.00
3	TO PROVIDE SKILL LABOUR & MATERIAL TO PREPARE & PAINT ALL NEW PARTS & PANELS	1		\$800.00	\$ 800.00	400	\$ 800.00
	PARTS						
1	TAIL GATE	1		\$1,638.00	\$ 1,638.00	/DT	\$ 1,638.00
2	TAIL GATE LOGO	1		\$45.00	\$ 45.00	/PIC	\$ 45.00
3	TAIL GATE MAZDA LOGO	1		\$46.00	\$ 46.00	/PIC	\$ 46.00
4	TAIL GATE 5 LOGO	1		\$37.00	\$ 37.00	/PIC	\$ 37.00
5	TAIL GATE SKYACTIVE LOGO	1		\$80.00	\$ 80.00	/PIC	\$ 80.00
6	REAR BUMPER	1		\$962.00	\$ 962.00	/cut	\$ 962.00
7	REAR BUMPER CLIPS	10		\$10.00	\$ 100.00	/PIC 30	\$ 100.00
8	REAR BUMPER SIDE RETAINER LH & RH	2		\$48.00	\$ 96.00	/PIC	\$ 96.00
9	REAR BUMPER REINFORCEMENT	1		\$156.00	\$ 156.00	7. XGR	\$ 156.00
10	REAR END PANEL	1		\$516.00	\$ 516.00	1. Xr	\$ 516.00
11	REVERSE SENSOR	1		\$250.00	\$ 250.00	cut 700	\$ 250.00 SW
				SUBTOTAL	\$ 5,726.00	SUBTOTAL	\$ 5,726.00
				GST 7%	\$ 400.82	GST 7%	\$ 400.82
				TOTAL	\$ 6,126.82	TOTAL	\$ 6,126.82

REMARKS: PLEASE TAKE NOTE IT MAY HAVE ADDITIONAL ITEM TO ADD ON AFTER REMOVE.

LKK Auto Consultants hence notify the Repairer of the following PRICE AS LISTED ABOVE.

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance company

(CUSTOMER'S SIGNATURE) COMPANY STAMP)

Acknowledged by Repairer

FOR DICKSON AUTO CARE CENTRE PTE LTD

(AUTHORISED SIGNATURE)



Thuan
82235769
27/4/22 1700
L15 for 5 days SWP

P: 2934
- 20%
= 2347.2
Sw + L: 1030
2347.2 + 1030
= 3377.2
- 20%
= 2701.76
= 2706