



發 福 摩 哆 車 房 HUAT HOCK MOTOR WORKSHOP

TP SMRT Denise.

BLOCK 3012, BEDOK NORTH AVE 4, #01-2054,
BEDOK INDUSTRIAL PARK E, SINGAPORE 489978.
Tel / Fax: 6445 2934 Hp: 8161 6988

BUSINESS REG NO. 375654/00C

Vehicle No : G86 8T02U	Accident Date : 20.4.22
Mileage :	make / Model : Toyota Hiace Van
	CHASSIC : KD#201 021 6249
Date :	Fax NO. : 6445 2934

Items			
1	RH Side Door Front Pillar Rgr	x	\$ 466.10
2	RH Side Door Dented	✓	\$ 1066.75
3	RH Side Door upper Roller Nm	x	\$ 110.40
4	RH Side Door Lower Roller Nm	x	\$ 201.35
5	RH Side Door Front Lock Dmgd.	38/ ✓	\$ 509.45
6	RH Side Door outer handle Nm	x	\$ 210.10
7	RH Side Door Rear Lock Nm	x	\$ 510.45
8	RH Side Door weather strip Nm	x	\$ 399.15
9	RH Rear Body Panel Rgr	x	\$ 1065.35
10	Rear Bumper Lt	✓	\$ 461.35
12	Rear Bumper RH retainer Nm	✓	\$ 110.35
13	Rear RH Rear Rm Cover Cut	120(SN)	\$ 201.10
14	Rear wheel beam Nm	+	\$ 345.10
15			
16	2019.45 S.N : 120.		
17	Len 25% : 151458		
18			
19	Special nett items.		
20			380
21	RH side Door Bread strider & Wording Nm		\$ 440
22	RH Body Panel strider & Wording		\$ 340 253
23	RH Rear tyre Nm	+	\$ 220
24		630	
25			
26			
27			
28			
29			



發 福 摩 多 車 房 HUAT HOCK MOTOR WORKSHOP

BLOCK 3012, BEDOK NORTH AVE 4, #01-2054,
BEDOK INDUSTRIAL PARK E, SINGAPORE 489978.
Tel / Fax: 6445 2934 Hp: 8161 6938
BUSINESS REG NO. 375654/00C

GBG 87024

Transfer of Side Door Mechanism	80	# 150.00
To check & rewiring system.	30	# 80.00
To remove & reinstall Body panel, Door striker & wording logo	120	# 220.00
To strengthen Body panel, realign on affected area and replace damage parts	700	# 1200.00
To spray paint on Pillar, Side Door, Body panel & etc.	700	# 1000.00
To remove & fix up Rear wheel beam	1630	# 180.00 x
Est to repair 6 days.		9487
Adrian G 1/2 26/04/22		
05 Page		
Total: 3894.58		
L/S: 3.1K.		

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: