



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBG 8702U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	RH SIDE DOOR FRONT PILLAR	TO REPAIR SEE LABOUR	466.10	-
1	RH SIDE DOOR	DENTED	1,066.75	1,066.75
1	RH SIDE DOOR UPPER ROLLER	NOT NECESSARY	110.40	-
1	RH SIDE DOOR LOWER ROLLER	NOT NECESSARY	201.35	-
1	RH SIDE DOOR FRONT LOCK	DAMAGED	509.45	381.00
1	RH SIDE DOOR OUTER HANDLE	NOT NECESSARY	210.10	-
1	RH SIDE DOOR REAR LOCK	NOT NECESSARY	510.45	-
1	RH SIDE DOOR WEATHER STRIP	NOT NECESSARY	399.15	-
1	RH REAR BODY PANEL	TO REPAIR SEE LABOUR	1,065.35	-
1	REAR BUMPER	CUT	461.35	461.35
1	REAR BUMPER RH RETAINER	NECESSARY	110.35	110.35
1	REAR WHEEL BEARING	NOT NECESSARY	345.10	-
	LESS 25% DISCOUNT		-	-504.86
			5,455.90	1,514.59
<b><u>SPECIAL NETT ITEMS</u></b>				
1	REAR RH REAR RIM COVER (SN)	CUT	201.10	120.00
1	RH SIDE DOOR BREAD STICKER & WORDING (SN)	NECESSARY	440.00	380.00
1	RH BODY PANEL STICKER & WORDING (SN)	NECESSARY	340.00	250.00
1	RH REAR TYRE (SN)	NOT NECESSARY	220.00	-
			1,201.10	750.00
<b><u>LABOUR</u></b>				
	TRANSFER OF SIDE DOOR MECHANISM.		150.00	80.00
	TO CHECK & REWIRING SYSTEM.		80.00	30.00
	TO REWIRE & REINSTALL BODY PANEL,DOOR STICKER & WORDING LOGO.		220.00	120.00
	TO STRAIGHTEN BODY PANEL,REALIGN ON AFFECTED AREA AND REPLACE DAMAGE PARTS.INCLUSIVE OF THE REPAIR OF RH SIDE DOOR FRONT PILLAR AND RH REAR BODY PANEL.		1,200.00	700.00
	TO SPRAY PAINTING ON PILLAR,SIDE DOOR,BODY PANEL & ETC.		1,000.00	700.00

Report Ref No. CS/SMR22003802/Aty3n2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REWIRE & FIX UP REAR WHEEL BEARING.	NOT NECESSARY	180.00	-
			2,830.00	1,630.00
GRAND TOTAL			9,487.00	3,894.59
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,100.00

Report Ref No. CS/SMR22003802/Aty3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.