



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ALLIANZ INSURANCE SINGAPORE PTE LTD 79 ROBINSON ROAD #09-01 SINGAPORE 068897			Ref: CS/AIS22003807/Avy3e2 Date: 14/07/2022 Code: AIS	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMW 3344M	Veh. Inspected	SMJ 199D
	Policy No.		Coverage (\$)	0.00
	Claim No.	2022 22004604FR	Excess (\$)	0.00
	Assign From	SHANTI	Assign Date	25/04/2022
2. Vehicle Particulars & Condition				
	Make & Model	B.M.W. 520I	c.c	1997
	Engine No.	HIDDEN	Year of Reg.	2014
	Chassis No.	WBA5A32070D335148	Colour	GREY
	Odometer	183624 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	245/45 R18	MICHELIN	6 mm
	L/H Front Tyre	245/45 R18	MICHELIN	6 mm
	R/H Rear Tyre	245/45 R18	MICHELIN	6 mm
	L/H Rear Tyre	245/45 R18	MICHELIN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	19/04/2022	Inspection Date	27/04/2022
	Survey held at	NEW ZEN WERKZ PTE LTD 3 KAKI BUKIT ROAD 1, #03-04, SINGAPORE 415935		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	