

NEW ZEN WERKZ PTE LTD

BLK 3 KAKI BUKIT RD 1 #03-04 EUNOS TECHNOLINK SINGAPORE 415935

26th April 2022

EE BENG LEONG

Blk 3 Kaki Bukit Road 1

03 - 04 Eunoss Technolink

Singapore 415935

TP Allianz
veron

WBASA320700335148

Accident date: 19th APRIL 2022

Estimated repair cost for vehicle no: SMJ199D BMW 520I

S/n	Qty	Items/Nett	U/price	Amount
1	1	Rear boot lid emble logo <i>3 new</i>		\$95.00 ✓
2	1	Rear boot lid 520I logo		\$60.00 ✓
3	2	Rear Boot Lid Number Plate Lamp <i>3 new</i>	\$35.00	\$70.00 x
4	1	Rear Boot Lid number plate		\$50.00 x
5	2	Rear tail lamp <i>new</i>	\$785.00	\$1,570.00 x
6	4	Rear tail lamp clips <i>new</i>	\$5.50	\$22.00 x
7	1	Rear bumper <i>Deland</i>		\$1,550.00 ✓
8	2	Rear Bumper Side Bracket <i>new</i>	\$185.00	\$370.00 x
9	4	Rear bumper reverse sensor <i>2 pieces damaged</i>	\$299.50	\$1,198.00 <i>599.</i>
10	1	Rear Bumper towing cover <i>new</i>		\$29.00 x
11	2	Rear Bumper Side reflector <i>new</i>	\$88.20	\$176.40 ✓
12	2	rear bumper side retainer <i>cracked</i>	\$325.00	\$650.00 <i>260.</i>
13	1	rear bumper reinforcement -plastic cover <i>cracked</i>		\$635.00 <i>245</i>
14	1	rear bumper centre beam <i>cracked</i>		\$255.00 <i>220</i>
15	1	rear control swift <i>new</i>		\$355.00 x
16	1	Rear Bumper reinforcement <i>Detected</i>		\$725.00 <i>690</i>
17	2	Rear Bumper reinforcement bracket <i>new</i>	\$255.00	\$510.00 x
18	1	Rear Bumper lower center cover <i>Detected</i>		\$425.00 <i>285.</i>
19	3	Rear Bumper lower center cover clips <i>new</i>	\$6.50	\$52.00 <i>20</i>
20	10	Rear bumper clips <i>new</i>	\$6.50	\$65.00 <i>30.</i>
21	1	Rear end panel <i>Repairs</i>		\$690.00 x
22	1	Rear End Panel Top Garnish <i>cracked</i>		\$215.00 ✓

4445.40
4000.86

Subtotal :- \$9,767.40

Labour charges

To remove & re-fix cushion

To remove & re-fix reverse sensor

To Check Wiring System

Tuff kote

Panel beating

Spray painting

To perform diagnostic test

LKK Auto Consultants hence notify the Repairer of the following:

- To survey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Subtotal :-

Total:-

\$120.00 *60*

\$120.00 *60*

\$60.00 *30*

\$120.00 *60*

\$800.00 *600*

\$800.00 *700.*

\$2,020.00

\$11,787.40

11,987.40

4.5K