

Steve CLKK)
27/4/22, 9.30am

m
3
Lys
PIP
Ry BLy

76996 - C00001

Klenco (Singapore) Pte Ltd

Attn: Mr Peter Beh
18 Gul Crescent

Singapore 629527

SERVICE ESTIMATE

SL: SERVICE SALES - PC

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 1

Inv.date. : 22/04/2022

WIP No. : 22136

Veh.In/Out:

*Tel.No. : Mobile: 96260071

Reg.No. : SBW71A

Reg.date : 27/03/2014

Mileage : 0

Chassis No: JN1BCAY51Z0450026

Closed by : Juan Paulo Bongon Ba

Svc Consultant :

Remarks : Klenco (Singapore) P

Op.No	Description	Mech	Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE REAR BUMPER, REINFO	0	800	1200.00	0		1,200.00	S
800	TO SPRAY REAR BUMPER, REINFORCEMENT, ETC	0	800	1800.00	0		1,800.00	S
280	TO CHECK WIRING INCLUDE RESETTNG OF ALL ELECTRICAL MODULES	0		498.00	0		498.00	S
	REAR BUMPER M37 M25	1.0	EA	2269.40	2042.46		2,269.40	S
	CLIP BUMPER REAR	15.0	EA	5.00	67.50		75.00	S
	REAR BUMPER FOAM	1.0	EA	417.50			417.50	S
	BRACKET BUMPER LH	1.0	EA	70.20			70.20	S
	BRACKET BUMPER RH	1.0	EA	70.20			70.20	S
	BUMPER BEAM REAR	1.0	EA	1489.00			1,489.00	S
	DIFFUSER ASSY	1.0	EA	101.80			101.80	S
	SENSOR-SCANNER	4.0	EA	289.00			1,156.00	S

Gross Total. 9,147.10

Labour Total 3,498.00
Parts Total 5,649.10
Package Total 0.00

Net..... 9,147.10
GST @ 7.0% 640.30
Total..... 9,787.40
Paid..... 0.00
Please Pay.. 9,787.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before and after painting
- To dispense paint and parts on a resurvey
- Parts must be replaced on a "no fault" basis
- No "no fault" basis for "no fault" basis
- Supply of materials must be authorized and
- Is subject to the terms and conditions of the Insurance Company

Wearnes Automotive Pte. Ltd.
45 Leng Kee Road, Singapore 159103 T 6430 4700 www.wearnes.com

Acknowledged by Repairer

Co reg no. 199501400R / GST reg no. M28920628X

Date:

Accident report SW08224L0001