

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ECICS Limited
10 Eunos Road 8
#09-04A Singapore Post Centre
Singapore 408600

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 26 Apr 2022

Preliminary Advice

Insured : SMR1833H

Vehicle No

TP Vehicle : SMP896T
No

Accident Date : 22/04/2022

Make : TOYOTA VIOS

Assignment Date : 25/04/2022

Date of : 25/04/2022

Est. Duration of : 10
Repair

Inspection

Inspection At : WAH HONG MOTORS & CREDIT PTE LTD (HQ)
38 TOH GUAN ROAD EAST, #01-57, ENTERPRISE HUB
SINGAPORE 608581

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross) :S\$ 14,439.25

Revised Amount :S\$ 10,072.50

Check Items (Estimated) :S\$ 1,269.00

Total :S\$ 11,341.50

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

Pre-Accident Value :S\$

COE / PARF Rebate :S\$

Salvage Value :S\$

Margin for Repair

:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.