

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/III22003813/GPA3Q2**Date:** 17/01/2023REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D20MFL0000326_01
<b>Claimant Vehicle No :</b>	JUV4751	<b>Insured Vehicle No :</b>	SNB4373X
Date of Loss:	16/03/2022	Nature of Claim:	TP
		Claim No:	MFL2022D0001358

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>JUV4751</b>	Engine No:	1P52QMI11L28001501
Make & Model:	WMOTO ES125, 125cc (WS125)	Chassis No:	PRWS12CBMA001790
Reg. Date:	15/11/2021 (Man. Year: 2021)	Odometer:	4410 km
Colour:	Black		
Engine Capacity:	125 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	70/90-14	Rear Tyre Size:	80/90-14
Front Left Side:	Komodo 6 mm	Rear Left Side:	Komodo 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	
<b>Approved Total (Overridden) (S\$)</b>		<b>1,200.00</b>		
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>1,200.00</b>	<b>-1,200.00</b>	
<b>+ Loss of Use (15.0 x S\$20.00/day) (S\$)</b>		300.00		
<b>+ Other Costs (S\$)</b>		60.00		
<b>Nett Liability (S\$)</b>		<b>1,560.00</b>		

INSPECTION

Date of Assignment:	25/04/2022	
Date Inspected:	26/04/2022	Inspected At: Sanfu Motor Pte Ltd (Kaki Bukit) 1 Kaki Bukit Ave 6, #02-43 Autobay @ Kaki Bukit Singapore 417883
Estimated Period of Repair:	0.0 days	

**Adjuster:** XING GUO QIANG**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

TOTAL LOSS DUE TO BODY STRUCTURE BENT AND BEYOND ECONOMICAL REPAIR. MV - RM4000 ~  
SGD1200

# REPAIR DETAILS

Reference		
Part Source:		
Parts:	N/A	WMOTO ES125 125cc (WS125) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for JUV4751)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >