



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

Finalization

ESTIMATE FOR SFF7777T

LONPAC INSURANCE BHD

MOTOR CLAIM DEPARTMENT
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555
62507388

Steve

Vehicle & Document Information

WIP No 56382
Reg No/Reg Date SFF7777T / 14/01/2021
Date In/Mileage 09/05/2022 / 46618
Chassis No W1N2533842F8428532
Engine No 26492080078122
Make/Model MB/GLC 300 4MATIC COUPE
Colour/Trim 028 890 Cavansite B/ 041 164 ARTICO Leat

Account No	Terms	Date/Time Printed	CSE	Operator		
WL001605	Credit	27/07/2022/ 18:32	AQ	305 / Alan Quek Ai Lun		
Description of Goods / Services			Qty	Unit Price	Disc%	Amount

M BPNSUN

POLICY NO/ACC DATE : 7210003636 // 22-04-2022
DRIVE IN: 25-04-2022 // TP CAR NO: YN9163J (LONPAC INSURANCE)
DATE IN/DATE SURVEY: 09-05-2022 // LKK STEVE
BY/AUTHORIZED ON : LKK HSIAO TONG // 29-04-2022

A BPILAB

USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO
STANDARD SETTINGS.NETT

A BPILAB

CHECK REAR LIGHTING SYSTEM AND CONDUCT WATER TEST FOR ANY LEAKAGE.NETT

A BPILAB

REMOVE & REPLACE REAR BUMPER & REPAIR REAR RIGHT FENDER

A BPIRES

RESPRAY REAR BUMPER, REAR RIGHT FENDER & REAR PETROL TANK FLAP

X REAR BUMPER

1.00 998.90 00.00 998.90

X RH/R FENDER SIDE TRIM

1.00 263.06 00.00 263.06

X RH/R TAIL LAMP

1.00 734.51 00.00 734.51

Alan Quek

Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center

DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272

Email: alan.quek@cyclecarriage.com.sg

Confirmed & accepted by

Nett 6,072.47
7% GST on 6072.47 425.07

Total Payable 6,497.54

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG