



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR22003820/Kvy3e2	
			Date: 27/06/2022	
			Code: SMR	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SHC 4459Z	Veh. Inspected	GBG 7640X
	Policy No.		Coverage (\$)	0.00
	Claim No.	TAX/04/22/2057	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	25/04/2022
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	TOYOTA DYNA (M)	c.c	2982
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	JTFAT35Y40K209345	Colour	WHITE / RED
	Odometer	92266 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	195 R15X8	TOYO	5 mm
	L/H Front Tyre	195 R15X8	TOYO	5 mm
	R/H Rear Tyre	155 R12X8 (D)	GRENLANDER	9/9 mm
	L/H Rear Tyre	155 R12X8 (D)	GRENLANDER	9/9 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	19/04/2022	Inspection Date	25/04/2022
	Survey held at	THIAM HENG HUAT PTE LTD 176 SIN MING DRIVE #05-14 SINGAPORE 575721		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	