

ASS. REC. BY:

REF:

SMO/22003827/Kg43

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop n/s Buddy Auto

of _____

Insured: 843A

Policy No. _____

Claims No. CMTD 2201399/54H

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<input checked="" type="checkbox"/>	<input type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value: 8152k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 03 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SJV5105P Yr Regn: 08, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (A) Wagon

Make: Audi Q5 TFSI c.c. 1894

Colour: M-Black A/C: Insured / Std / NI / NA

Sp. Reading: 52322 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WATU 888FY4J 2170329

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235/55R19
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear
R/Bal. <u>9</u> mm		R/Bal. <u>9</u> mm
L/Bal. <u>9</u> mm		L/Bal. <u>9</u> mm

D.O.A. 23/4/22 D.O.I. 26/4/2022

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or FR N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

9/5 CIDP @ 27501 Caber (Red # 2291, 45%)

10/5/22 @ 4.48pm revised to Hwang Shiang Yi by email.

Date/Time, File Pass to?

1) 10/5/22

Date/Time, File Return to?

2)

: Preli. Report

: Final Report

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

\$ + RS. \$

Fuel

Others

TOTAL

Add Fee: : Site Insp (\$)

: Interview (\$)

: Tech Invs (\$)

: Weekend (\$)

Report Format: TP

Lump Sum / I.B.F. (\$) 2750

Ready Auto Care Pte Ltd - We Care For All Your Car Needs

Blk 10 # 03-06 AMK Auto Point, Ang Mo Kio Ind Park 2A, Ang Mo Kio Ave 5. Singapore 568047

Tel : 64810304 Fax : 64815587

Reg No : 200600989K

Sompo Insurance
Motorcar Claim Department

*Not withold
L1 Imp @ 275ch
Resurvey After Paint*

Estimate Repair

Date : 25/4/2022


Accident Involving SJV5105P & SME3756Y On 23/04/2022 Along Ngee Ann City

SJV5105P

Audi Q5

Item	Descriptions	Amount
	Front Bumper <i>2342.80</i>	<i>Price</i> \$ 2,364.00 ✓
1	FL Headlamp Nozzle Cover	\$ <i>3</i> 335.00 X
2	FL Fog Lamp Cover <i>464.40</i>	<i>Nett Price</i> \$ 577.00 ✓
Total For Parts (Special Nett)		\$ 3,276.00
 <u>S/N Item (s)</u>		<i>58</i>
1	Front Bumper Clips - 1 Set	\$ <i>Nett</i> 35.00 ✓
Total For Nett Items		\$ 35.00
 <u>Labour & Misc</u>		
1	To Remove & Transfer Front Wire Harness For Headlamp, Horn, Fog Lamp, Outside Temperatur Sensor, Headlight Washer Assy And Front Parking Aid	\$ <i>280</i> 480.00
2	To Dismantle And Renew Front Bumper Assy, Re-organise Front Crash Management Components. Reinstall All Parts Removed	\$ <i>261</i> 550.00 X
3	To Spray Front Bumper, Lower Spoiler And Wheel Arch Trims	\$ <i>450</i> 600.00
Total		\$ 1,730.00

Sulynn - 96606551



No Of Days For Repair 3 ✓

Total Repair Cost \$ 5,041.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: