

NK before Resurvey

b02 - 192

J.E.W MOTORS PTE LTD

Address: 60 Jalan Lam Huat, #03-72
CARROS CENTER, Singapore 737869

Repair Quotation

Vehicle number: SLD30588
Model and make: Honda Grace
Chassis number: GM61001049

Insurance company:

No.	Spare parts	Qty	Amount
1	Rear bumper	1	\$ 947.80 X R
2	Rear bumper clips	1set	\$ 60.00 / noc
3	Rear bumper RH retainer	1	\$ 28.50 / noc
4	Rear bumper LH retainer	1	\$ 28.50 X Svc
5	RH taillamp assy	1	\$ 411.30 X Svc
6	Rear windscreen glass rubber moulding	1	\$ 101.80 / noc
7	RH rear fender	1	\$ 903.50 / DT
8	RH rear fender quarter garnish	1	\$ 34.20 / noc
9	RH rear fender quarter garnish clips	1set	\$ 25.00 / noc
10	RH rear fender splash shield	1	\$ 34.20 / X Svc
11	RH rear fender splash shield clips	1set	\$ 28.00 / noc
12	RH rear fender inner trim	1	\$ 155.30 / X Svc
13	RH rear fender inner trim clips	1set	\$ 50.00 / noc
14	RH rear sport rim (Original)	1	\$ 783.20 / scr 350
15	RH rear sport rim centre cap	1	\$ 33.40 X Svc
16	Rear axle beam	1	\$ 1,096.80 X Svc
17	Rear RH shock absorber	1	\$ 198.60 X Svc
18	Rear RH wheel bearing	1	\$ 198.70 X Svc
19	Rear RH wheel hub	1	\$ 250.30 X Svc
20	RH rear door	1	\$ 873.50 / DT
21	RH rear door frame black sticker	1set	\$ 78.60 / noc
22	RH rear door outer moulding	1	\$ 77.50 / noc
23	RH rear door upper hinge	1	\$ 66.50 X Svc
24	RH rear door lower hinge	1	\$ 66.50 X Svc
25	RH rear door checker	1	\$ 55.60 / noc
26	RH rear door inner trim board	1	\$ 341.20 / cut
27	RH rear door inner trim board clips	1set	\$ 60.00 / noc
28	RH rear door glass regulator gear	1	\$ 188.70 / BT 300
29	RH rear door glass regulator gear motor	1	\$ 353.50 / X Svc
30	RH rear door weatherstrip	1	\$ 93.20 / X Svc
31	RH rear door lower seal	1	\$ 12.30 / noc
32	RH rear door glass channel	1	\$ 44.50 / X N W
33	RH rear door outer handle	1	\$ 89.70 X Svc
34	RH rear door inner step garnish	1	\$ 66.10 / X Svc
35	RH rear door speaker	1	\$ 155.60 X Svc
36	RH rear door lock	1	\$ 164.80 X Svc
37	RH rear door lock catch	1	\$ 56.80 X Svc

38	RH rear door plastic cover seal	1	\$	33.70	XSC
39	RH side door centre pillar	1	\$	607.80	XSC
40	RH side door centre pillar inner lower garnish	1	\$	90.70	XSC
41	RH side door centre pillar inner lower garnish clips	1set	\$	30.00	XSC
42	RH side door centre pillar seat belt	1	\$	788.30	XSC
43	RH front door	1	\$	873.50	DT
44	RH front door frame black sticker	1set	\$	78.60	XSC
45	RH front door outer moulding	1	\$	77.50	XSC
46	RH front door upper hinge	1	\$	66.50	XSC
47	RH front door lower hinge	1	\$	66.50	XSC
48	RH front door checker	1	\$	55.60	XSC
49	RH front door inner trim board	1	\$	341.20	XSC
50	RH front door inner trim board clips	1set	\$	60.00	XSC
51	RH front door glass regulator gear	1	\$	188.70	XSC
52	RH front door glass regulator gear motor	1	\$	353.50	XSC
53	RH front door weatherstrip	1	\$	93.20	XSC
54	RH front door lower seal	1	\$	12.30	XSC
55	RH front door glass channel	1	\$	44.50	XSC
56	RH front door outer handle	1	\$	89.70	XSC
57	RH front door inner step garnish	1	\$	66.10	XSC
58	RH front door speaker	1	\$	155.60	XSC
59	RH front door lock	1	\$	164.80	XSC
60	RH front door lock catch	1	\$	56.80	XSC
61	RH rear door plastic cover seal	1	\$	33.70	XSC
62	RH rear sport rim (Original)	1	\$	783.20	XSC
63	RH rear sport rim centre cap	1	\$	33.40	XSC
64	RH front shock absorber	1	\$	233.10	XSC
65	RH front lower arm	1	\$	348.40	XSC
66	RH front knuckle arm	1	\$	441.30	XSC
67	RH front wheel bearing	1	\$	113.80	XSC
68	RH front tie rod end	1	\$	78.00	XSC
69	RH side mirror assy	1	\$	799.40	XSC
70	RH front fender	1	\$	411.60	XSC
71	RH front fender splash shield	1	\$	113.40	XSC
72	RH front fender splash shield clips	1set	\$	50.00	XSC
73	Front bumper	1	\$	903.60	XSC
74	Front bumper clips	1set	\$	50.00	XSC
75	Front bumper RH side retainer	1	\$	33.20	XSC

\$ 17,034.90
 less parts 20% \$ 3,406.98
 Total \$ 13,627.92

No.	Spare parts	Qty	Special Nett
1	Rear windscreen glass sealant	1	\$ 80.00 XSC
2	Rear windscreen glass inner seal	1	\$ 50.00 XSC

3	Rear bumper reverse sensor	1 set	\$	380.00 KBN
4	RH rear tyre	1	\$	650.00 KBN
5	RH rear fender seal	1	\$	80.00 SC 9x
6	RH rear door sun visor	1	\$	280.00 30 P
7	RH front door sun visor	1	\$	280.00 KBN
8	RH side door centre pillar seal	1	\$	80.00 KBN
9	RH front tyre	1	\$	650.00 KBN

LABOUR

1	Labour charges to provide workmanship cut / weld and replacing of parts	\$	2,600.00 1700
2	Spray paint on affected and consistent areas	\$	1,800.00 1200
3	Check wiring and lighting system	\$	120.00 30
4	Apply rust chemical on affected areas	\$	180.00 40
5	Remove and reinstall rear windscreen glass	\$	280.00 170
6	Remove and reinstall rear bumper reverse sensors	\$	120.00 30
6	Remove and replace rear inner trims and garnish	\$	350.00 70
7	Remove and reinstall fuel tank and pipes	\$	280.00 XBN
8	Remove and replace rear undercarriage parts	\$	550.00 XBN
9	Adjust wheel alignment system	\$	120.00 60
10	Remove and reinstall roof lining and seats	\$	550.00 70
11	Remove and replace RH rear door inner parts to new door	\$	220.00 70
12	Remove and replace RH front door inner parts to new door	\$	220.00 70
13	Remove and replace front undercarriage parts	\$	650.00 XBN
14	Replace, re-balance and test RH rear and RH front sport rim and tyres	\$	150.00 40

F:6300
AD: 8

Thuan
822 35769
LIS 8 days up
27/4/22 1318

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Total: 24,347.92

Acknowledged by Repairer
Signature: _____