### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road, #16-00 Springleaf Tower

Our File No: CS/CTI22003830/KTY3E2

Singapore 079909 **Date:** 17/05/2022

**REFERENCE** 

Insured/Claimant: Sim Pitt Chen Gregory Policy No: DMPCSNW00163782101

Date of Loss: 18/04/2022 Nature of Claim: OD Claim No: SNM22D202675/C01/LEEPG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SMD212E

Make & Model: SUBARU FORESTER, 2.0 XT (A) Engine No: FA20J941110

Reg. Date: 30/03/2015 (Man. Year: 2014) Chassis No: JF1SJGK85EG039929

Colour: Metallic Grey Odometer: 155530 km

Engine Capacity: 1998 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 225/55 R18 Rear Tyre Size: 225/55 R18
Front Left Side: Continental 8 mm Rear Left Side: Continental 8 mm
Front Right Side: Continental 8 mm Rear Right Side: Continental 8 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS      |                              | Repairer's | Adjuster's | Difference | Diff % |
|---------------------|------------------------------|------------|------------|------------|--------|
| Parts               |                              | 24,740.00  | 15,805.00  | 8,935.00   | 36.12  |
| Miscellaneous Items |                              | 88.00      | 68.00      | 20.00      | 22.73  |
| Labour              |                              | 2,587.20   | 2,587.20   | 0.00       | 0.00   |
| Paintwork Labour    |                              | 1,429.24   | 1,429.24   | 0.00       | 0.00   |
| Towing              |                              | 0.00       | 0.00       | 0.00       |        |
|                     | Calculated Gross Total (S\$) | 28,844.44  | 19,889.44  | 8,955.00   | 31.05  |
|                     | - Excess (S\$)               | 0.00       | 250.00     | -250.00    |        |
|                     | (S\$)                        | 28,844.44  | 19,639.44  | 9,205.00   | 31.91  |
|                     | + GST 7.00/0.00% (S\$)       | 2,019.11   | 0.00       | 2,019.11   | 100.00 |
|                     | Nett Amount (S\$)            | 30,863.55  | 19,639.44  | 11,224.11  | 36.37  |

INSPECTION

Date of Assignment: 25/04/2022 Present Location: S & H Motor Pte Ltd (Sin Ming)

S & H Motor Pte Ltd (Sin Ming)

Date Inspected: 26/04/2022 Inspected At: 160 Sin Ming Drive #07-02, Sin Ming AutoCity

Cingapara 575722

Singapore 575722

Estimated Period of Repair: 0.0 days

Adjuster: KENNETH KONG Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

#### TOTAL LOSS ASPECT

Market Value: \$51,000.00

OMV: \$17,813.00

PARF Rebate (1): \$10,687.00

Quota Premium Paid: \$71,889.00

COE Rebate (2): \$21,160.00

Total Rebate (1) + (2) =: \$31,847.00

The total amount incurred will be Market Value \$51,000.00 minus Total Rebate \$31,847.00 = \$19,153.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

## **REPAIR DETAILS**

### Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 17 May 2022)

Parts: M1-SUV SUBARU FORESTER 2.0 XT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMD212E)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### **Recommended Parts**

| No. Qty Part No.  | Particulars | Condition         | Repairer's  | Amount       |
|-------------------|-------------|-------------------|-------------|--------------|
| 1 1               | *Parts      |                   | 24,740.00 F | *15,805.00 F |
| F=Franchise part. |             | Total Parts (S\$) | 24,740.00   | 15,805.00    |
|                   |             |                   |             |              |

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

| No Qty Particulars            |                         | Repairer's | Amount   |
|-------------------------------|-------------------------|------------|----------|
| Miscellaneous Items           |                         |            |          |
| 1 1 <b>Misc</b>               |                         | 88.00      | 68.00    |
|                               | Sub Total (S\$)         | 88.00      | 68.00    |
| Recommended Labour            |                         |            |          |
| No Particulars                | Lab.Type                | Repairer's | Amount   |
| Paintwork Labour              |                         |            |          |
| 1 Labour for paintwork        | New                     | 1,429.24   | 1,429.24 |
| <u>Labour Items</u>           |                         |            |          |
| 2 Labour for panel/mechanical | New                     | 2,587.20   | 2,587.20 |
|                               | Gross Labour Cost (S\$) | 4,016.44   | 4,016.44 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >