

ASS. REC. BY:

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

days

Res.: Yes or No

Lum Sum: _____

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: _____

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: _____

Colour _____

Sp. Reading _____

Eng/No: _____

C/No: _____

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD / R/Rim or

Tyre Size: F: _____

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. _____

L/Bal. _____

D.O.A. _____

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S body & 1st o/s

The U/C / Chassis frame / Body Structure affected due to collision.

N/S	O/S

Date / Time

Action / Instruction

26/4 W/esp sent unable to locate 2nd party

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trlp: _____

Survey Fee: _____

Transportation: _____

Add Fee: _____

: Site Insp (\$ _____)

: Interview (\$ _____)

: Tech Invs (\$ _____)

: Weekend (\$ _____)

: Fixing

: Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ _____)

Report

0212

23 PM

nce

ATOR

ATS
NTR

GD/h
ce SGD

21.00
37.80

8.40
12.60
29.40

4.20
29.40

8.40

2022

S&H Motor Pte Ltd
160 Sin Ming Drive #07-02
Sin Ming Autocity
Singapore 575722

Insurer Reference:
Repairer Reference: 047398
Date calculated: 22/04/2022 4:23 PM

Full Report
✓ Registration: SMD212E
Printed: 22/04/2022 4:23 PM

Summary Information

Claim			
Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	SH Motor	Currency:	SGD
Claim Reference:		Date of Incident:	18/04/22
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle
 Manufacturer: SUBARU
 Model: FORESTER (SJ)
 Sub Model: BASE MODEL
 Model Sheet Number: 62 71 01
 Registration: SMD212E
 VIN number: JF1SJGK85EG039929
 Odometer:

Model Specs

FROM 03.2017	AUTO AIR CON	START & STOP SYSTEM	D/MIRROR W/INDICATOR
6 SPEAKER	SPEAKER "HARMANK"	XENON HEADLAMPS	FOG LAMPS
SIDE REPEATER LAMP	HEADLAMP WASHERS	WINDSCREEN HEATED	HEATED FRONT SEATS
WINDSCREEN W/SENSOR	FRONT CAMERA	REAR BUMPER COVER	AUTO TAILGATE CONTR
DETACHABLE TOW BAR	LWR T-GATE MLDG CHR	MIRROR HSG SET	1995CCM 110KW
SYSTEM "EYESIGHT"	WHEELS 7J X 17 ALU	HEAD AIRBAG	SIDE AIRBAGS
FRONT MUDFLAPS	TWO COAT METALLIC	PREPARE OFF VEHICLE	

*Not Authorised
 Ex 8250L
 May be 7/6001*

Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
EI0004R	R + R FRONT BUMPER		5.0	21.00
EI0004R ZAX	RENEW FRONT BUMPER		9.0	37.80
	INCLUDES: R + R NECESSARY ATTACHED PARTS, RENEW IF NECESSARY			
NO NUMBER	R + R BONNET		2.0	8.40
NO NUMBER	R + R FRONT BUMPER SUPPORT		3.0	12.60
EB0002R ZAX	R + R L/F WING		7.0	29.40
	INCLUDES: R + R HEADLAMP AND WHEELARCH TRIM			
EI0015R ZAX	R + R L/SILL MOULDING		1.0	4.20
EB0002R ZAX	R + R R/F WING		7.0	29.40
	INCLUDES: R + R HEADLAMP AND WHEELARCH TRIM			
NO NUMBER	ADJUST HEADLAMPS		2.0	8.40

Code	Description	WU	Price
AB0008R)	R + R LEFT AIR BAG SENSOR	2.0	8.40
GW0006R)	R + R WINDSCREEN	26.0	109.20
	INCLUDES: R + R ALL ATTACHED PARTS		
NO NUMBER	R + R L/ROOF RAIL	3.0	12.60
EB0015R ZAX	R + R LEFT ROOF MOULDING	3.0	12.60
AB0010R)	R + R L/HEAD AIRBAG	1.0	4.20
EB0003R	RENEW L/F DOOR	22.0	92.40
	INCLUDES: R + R DOOR		
EB0006R	RENEW L/R DOOR	18.0	75.60
	INCLUDES: R + R DOOR		
SB0001R	R + R RIGHT FRONT SEAT BELT	2.0	8.40
NO NUMBER	RENEW L/A-PILLAR CPL	75.0	315.00
NO NUMBER	RENEW L/SILL CPL	60.0	252.00
NO NUMBER	RENEW L/OUTER B-PILLAR	84.0	352.80
NO NUMBER	RENEW L/R SIDE PANEL	90.0	378.00
	INCLUDES: WHEELARCH TRIM, TAILLAMP AND TRIMS IN REPAIR AREA REMOVE AND REFIT		
GW0008R)	R + R LEFT REAR SIDE WINDOW GLASS	15.0	63.00
NO NUMBER	R + R REAR BUMPER	2.0	8.40
EI0006R ZAX	REAR BUMPER (REMOVED) RENEW	2.0	8.40
	INCLUDES: REQUIRED ATTACHED PARTS REMOVE AND REFIT		
NO NUMBER	R + R TOWING BAR	15.0	63.00
NO NUMBER	R + R TAILGATE	3.0	12.60
EI0039R	R + R HEADLINING	11.0	46.20
	INCLUDES: R + R SEATS AND ALL ATTACHED PARTS		
NO NUMBER	DETACH + REFIT LEFT FLOOR CARPET	2.0	8.40
AB0006R	R + R AIRBAG CONTROL UNIT	4.0	16.80
EI0025R	R + R INSTRUMENT PANEL	20.0	84.00
	INCLUDES: R + R GLOVE BOX, LOWER DRIVER SIDE TRIM, INSTRUMENT PANEL CONSOLE AND CENTRE CONSOLE		
SE0005R)	R + R LEFT FRONT SEAT BACKREST	3.0	12.60
NO NUMBER	R + R LEFT FRONT SEAT BACK REST COVER	3.0	12.60
IN0004R	R + R INTAKE PIPE	1.0	4.20
EX0001R)	DETACH + REFIT EXHAUST SYSTEM	2.0	8.40
EX0001R)	R + R FRONT EXHAUST PIPE	5.0	21.00
NO NUMBER	R + R L/F WHEEL	1.0	4.20
NO NUMBER	R + R R/F WHEEL	1.0	4.20
NO NUMBER	FIT LEFT FRONT RIM AND/OR TYRE (WHEEL REMOVED)	5.0	21.00
	INCLUDES: BALANCING WHEEL		
NO NUMBER	FIT RIGHT FRONT RIM AND/OR TYRE (WHEEL REMOVED)	5.0	21.00
	INCLUDES: BALANCING WHEEL		
NO NUMBER	DETACH + REFIT FRONT CONTROL ARM	1.0	4.20
PS0005R)	R + R STEERING BOX	3.0	12.60
PS0005R)	RENEW STEERING BOX (REMOVED)	5.0	21.00
FS0006R)	R + R FRONT AXLE CROSSMEMBER	12.0	50.40
	INCLUDES: R + R FRONT WHEELS, SUPPORTING FRAME, FRONT EXHAUST PIPE AND STABILIZER, DETACH + REFIT TIE ROD ENDS, CONTROL		

Description

ARMS, STEERING SPINDLE AND POWER
STEERING PIPES

		WU	Price SGD
DS00105)	DETACH + REFIT L/F AND R/F AXLE SHAFT	2.0	8.40
NO NUMBER	DETACH + REFIT L/F AXLE SHAFT	1.0	4.20
DS0010R)	R + R L/F AXLE SHAFT	3.0	12.60
NO NUMBER	DETACH + REFIT R/F AXLE SHAFT	1.0	4.20
DS0010R)	R + R R/FRONT AXLE	3.0	12.60
DS0020R ZAX	R + R L/F STEERING KNUCKLE	1.0	4.20
DS0020R ZAX	RENEW L/F STEERING KNUCKLE	4.0	16.80
DS0020R ZAX	R + R R/F STEERING KNUCKLE	1.0	4.20
DS0020R ZAX	RENEW R/F STEERING KNUCKLE	4.0	16.80
NO NUMBER	DETACH + REFIT FRONT SPRING STRUT	1.0	4.20
FS0004D)	R + R L/F STRUT	5.0	21.00
FS0004D)	DIS + ASS L/F SPRING STRUT	3.0	12.60
FS0004D)	R + R R/F STRUT	5.0	21.00
FS0004D)	DIS + ASS R/F SPRING STRUT	3.0	12.60
NO NUMBER	R + R L/R WHEEL	1.0	4.20
NO NUMBER	FIT LEFT REAR RIM AND/OR TYRE (WHEEL REMOVED)	5.0	21.00
	INCLUDES: BALANCING WHEEL		
DS0006R)	R + R LEFT REAR WHEEL HUB	10.0	42.00
NO NUMBER	DISS/ASS REAR SUSPENSION STRUT	1.0	4.20
RS0011R)	DETACH + REFIT REAR LONGITUDINAL LINK	1.0	4.20
GW0006R)	ADD ON PARTS ADAS: CALIBRATE	13.0	54.60
0471	BONNET REPAIR	5.0*	21.00

Labour Cost**Panel / Mechanical Labour**

Hrs WU
61.60 616.0

2,587.20

Total of Labour

2,587.20

Paint

Paint Work

SYSTEM AZT**Time Basis 10 WU/h**

Code	Description - TWO COAT METALLIC	WU	Price SGD
	BONNET NEW PART PAINTING	24.0	
	L/F WING NEW PART PAINTING	10.0	
	R/F WING NEW PART PAINTING	10.0	
	LEFT FRONT DOOR NEW PART PAINTING	18.0	
	L/R DOOR NEW PART PAINTING	16.0	
	L/SILL PANEL NEW PART PAINTING	16.0	
	L/OUTER A-PILLAR NEW PART PAINTING	17.0	
	L/OUTER B-PILLAR NEW PART PAINTING	16.0	
	L/RR SIDE PANEL NEW PART PAINTING	25.0	
	FRONT BUMPER NEW PART PAINT K1G	22.0	
	FRT BUMPER TRIM CAP NEW PART PAINT K1R	3.0	
	R/H-LAMP WASHER LID NEW PART PAINT K1G	4.0	
	REAR BUMPER NEW PART PAINT K1G	16.0	

Paint Material Per Part

Code	Description	Price SGD
0471	BONNET NEW PART PAINTING	80.50
0741	L/F WING NEW PART PAINTING	19.61

Paint Material Per Part

Code	Description	Price SGD
		19.61
0742	R/F WING NEW PART PAINTING	54.70
1481	LEFT FRONT DOOR NEW PART PAINTING	44.89
1781	L/R DOOR NEW PART PAINTING	15.40
2101	L/SILL PANEL NEW PART PAINTING	17.60
2237	L/OUTER A-PILLAR NEW PART PAINTING	15.95
2279	L/OUTER B-PILLAR NEW PART PAINTING	33.55
3481	L/RR SIDE PANEL NEW PART PAINTING	71.44
0281	FRONT BUMPER NEW PART PAINT K1G	0.49
0301	FRT BUMPER TRIM CAP NEW PART PAINT K1R	0.57
0626	R/H-LAMP WASHER LID NEW PART PAINT K1G	47.63
2581	REAR BUMPER NEW PART PAINT K1G	

Labour Cost - Paint

	Hrs	WU	Price SGD
Factor	42.00 SGD/h		
Time Paint		197.0	
Preparation Main Work Metal	2.50	25.0	105.00
Preparation Comp. Work Plastic	0.80	8.0	33.60
Total	10 WU/h	230.0	966.00

Material Cost - Paint

	Price SGD
New Part Painting	301.81
New Part Painting - Plastic K1R	0.49
New Part Painting - Plastic K1G	119.64
Material-constant Metal Preparation	28.60
Material-constant Plastic	12.70
Total	463.24

Spare Parts

Code	Description	Part Number	Part Source	prices as at 2015-06-01	Price SGD
0281	FRONT BUMPER	57709SG030	Original	CM	360.00 ✓
0298	R/FOG LAMP COVER	57731SG020	Original	my	65.00 ✓
0301	FRT BUMPER TRIM CAP	57731SG220	Original	my	20.00 ✓
0320	R/F INN BUMPER BRKT	57707SG020	Original	DT	20.00 ✓
0333	FRT BUMPER ABSORBER	57722SG020	Original		105.00 ?
0340	FRT BUMPER SUPPORT	57711SG0009P	Original		240.00 ?
0562	RIGHT HEADLAMP ASSY	84002SG002	Original	my Bv	1,100.00 ✓
0568	R/HEADLAMP BRACKET	57707SG000	Original		40.00 ?
0618	R/H-LAMP WASHER JET	86636SG301	Original		75.00 ?
0626	R/H-LAMP WASHER LID	86636SG340E1	Original		55.00 ?
0640	R/F FOG LAMP	84912AJ310	Original	my CM	180.00 ✓
0741	L/F WING	57120SG0109P	Original	Bz	380.00 ✓
0742	R/F WING	57120SG0009P	Original	R	190.00 x
0843	L/F WHEELHOUSE COVER	59110SG031	Original	CM	90.00 ✓
0844	R/F WHEELHOUSE COVER	59110SG021	Original	CM	95.00 ✓
1411	WINDSCREEN BOND KIT KNGKWI2				0.00
1413	FRT SCREEN MNTG KIT USE SINGLE PARTS				

	Description	Part Number	Part Source	Price SGD
	LEFT RETAINER	65035AJ010		0.00
	RIGHT RETAINER	65035AJ000		0.00
1481	LEFT FRONT DOOR	60009SG0529P	Original	By 850.00 ✓
1487	L/F UPPER DOOR HINGE	60079AG014	Original	By 45.00 ✓
1495	L/F LOWER DOOR HINGE	60079SG013	Original	By 45.00 ✓
1505	L/F DOOR CHECK	61124SG005	Original	By 45.00 ✓
1513	L/F LOWER DOOR SEAL	63511SG011	Original	Tn 110.00 ✓
1565	L/F OUTER HANDLE	61160FJ000B7	Original	Sm 120.00 X
1567	L/F INN DOOR HANDLE	61142FJ010	Original	Sm 10.00 X
1655	L/F DOOR REAR STRIP	90422SG050	Original	20.00 ?
1657	L/F UPP DOOR STRIPE	90422SG030	Original	20.00 ?
1659	L/F DOOR FRONT STRIP	90422SG010	Original	10.00 ?
1687	L/F DOOR MOULDING	91112SG232	Original	Nit 290.00 ✓
1707	L/DOOR SPEAKER	86301SG100	Original	280.00 ?
1737	L/DOOR MIRROR	91026SG371	Original	Sm 650.00 X
1777	L/F DOOR FRAME SEAL	63571SG001	Original	Nm 110.00 ✓
1781	L/R DOOR	60409SG0119P	Original	By 480.00 ✓
1787	L/R UPPER DOOR HINGE	60479FJ012	Original	R 40.00 X
1795	L/R LOWER DOOR HINGE	60479FG032	Original	R 40.00 X
1805	L/R DOOR CHECK	62124FJ001	Original	Sm 80.00 X
1817	L/R LWR DOOR SEAL	63512SG011	Original	Sm 130.00 X
1847	L/R WINDOW	61042SG210	Original	195.00 ?
	REGULATOR			Sm 20.00 X
1949	L/R DOOR REAR STRIP	90422SG110	Original	Sm 25.00 X
1951	L/R DOOR FRONT STRIP	90422SG070	Original	Sm 20.00 X
1953	L/R UPP DOOR STRIPE	90422SG090	Original	NIT 130.00 ✓
1987	L/R DOOR MOULDING	91112SG152	Original	By 450.00 ✓
2101	L/SILL PANEL	51449SG0109P	Original	480.00 ?
2237	L/OUTER A-PILLAR	51419SG0109P	Original	480.00 ?
2279	L/OUTER B-PILLAR	51429SG0109P	Original	Aug 10/17 380.00 ✓
2581	REAR BUMPER	57704SG012	Original	NIT 20.00 ✓
2619	L/R OUT BUMPER BRKT	57707SG090	Original	By 1,150.00 ✓
3481	L/RR SIDE PANEL	51439SG0119P	Original	0.00
3817	L/UPP SIDE WDW SEAL	65245SG020	Original	0.00
3821	L/S WINDOW BOND KIT	KNGKWI1		
3863	L/SIDE WDW MNTG KIT	USE SINGLE PARTS		
3867	L/SIDE WINDOW CLIPS	65254SG000		0.00
3871	L/SIDE WINDOW CLIPS	65254AE000		0.00
3873	L/SIDE WINDOW CLIPS	65235FJ000		0.00
4201	L/R WHEELHOUSE	59122SG070	Original	80.00 ?
	COVER			
4319	L/F AIRBAG SENSOR	98231SG010	Original	Nm 120.00 ✓
4327	L/SIDE AIRBAG SENSOR	98235SG030	Original	Nm 120.00 ✓
4589	L/F BACKREST COVER	64150SG630VH	Original	Tn 400.00 ✓
4607	L/SIDE AIRBAG	98201SG010	Original	ROTH 750.00 ✓
4627	L/HEAD AIRBAG	98251SG010	Original	4 850.00 ✓
4661	L/F SEAT BELT	64622SG031VH	Original	400.00 ?
4662	R/F SEAT BELT	64622SG021VH	Original	400.00 ?
4811	L/HEAD AIRBAG SENSOR	98235SG010	Original	Nm 120.00 ✓
4941	L/A-PILLAR TRIM	94010SG010LO	Original	380.00 ?
4957	HEADLINING	94415SG002LO	Original	Tn 750.00 ✓
7031	L/DRIVE SHAFT CPL	28321SG010	Original	850.00 ?
7032	R/DRIVE SHAFT CPL	28321SG010	Original	850.00 ?
7053	L/F LWR AXLE ARM	20202SG012	Original	By 320.00 ✓
7054	R/F LOWER AXLE ARM	20202SG002	Original	Nm 320.00 ✓
7077	L/FR SHOCK ABSORBER	20310SG110	Original	By 390.00 ✓

Code	Description	Part Number	Part Source	Price SGD
7078	R/FR SHOCK ABSORBER	20310SG100	Original	390.00
7081	L/F STEERING KNUCKLE	28313SC011	Original	190.00
7082	R/F STEERING KNUCKLE	28313SC001	Original	190.00
7091	L/F SPRING LEG BRG	20320FG003	Original	70.00 ?
7092	R/F SPRING LEG BRG	20320FG003	Original	70.00 ?
7131	L/F WHEEL HUB	28373FL010	Original	160.00
7132	R/F WHEEL HUB	28373FL010	Original	160.00
7201	L/FR WHEEL	28111SG110	Original	550.00
7202	R/FR WHEEL	28111SG110	Original	550.00
7261	FRONT STABILISER	20401SG000	Original	230.00 ?
7267	L/F STABILISER BUSH	20414SG001	Original	20.00 ?
7268	R/F STABILISER BUSH	20414SG001	Original	20.00 ?
7277	L/F STABI LINKAGE	20470SA001	Original	65.00 ?
7278	R/F STABI LINKAGE	20470SA001	Original	65.00 ?
7300	STEERING GEAR	34110SG010	Original	1,400.00 ?
7440	AIRBAG CONTROL UNIT	98221SG220	Original	2,800.00
9181	L/R WHEEL HUB	28473FL040	Original	130.00 ?
9305	L/R STRG KNUCKLE	28411SG011	Original	190.00 ?
9551	L/RR WHEEL	28111SG110	Original	550.00

f: OEM Parts
n: Non-OEM Parts
u: Used parts

Savings	0.00
Subtotal	24,640.00
Fixed Sundry Parts Price	100.00
Total	24,740.00

Code	Description	Price SGD
1000	L/R Q-GLASS INN SEAL LH REAR FENDER	28.00*
1001	L/R Q-GLASS SEALANT LH REAR FENDER	60.00*
Total Extras		88.00

Apply for PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	562F

Vehicle Details

Vehicle No.:	SMD212E
Vehicle to be Exported:	Yes
Intended Deregistration Date:	19 Apr 2022
Vehicle Make:	SUBARU
Vehicle Model:	SUBARU FORESTER 2.0XT
Primary Colour:	Grey
Manufacturing Year:	2014
Engine No.:	FA20J941110
Chassis No.:	JF1SJGK85EG039929
Maximum Power Output:	177.0 kW (237 bhp)
Open Market Value:	\$17,813.00
Original Registration Date:	30 Mar 2015
First Registration Date:	30 Mar 2015
Transfer Count:	1
Actual ARF Paid:	\$17,813.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Mar 2025
PARF Rebate Amount:	\$10,687.00

Intended COE Rebate Details

COE Expiry Date:	29 Mar 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$71,889.00
COE Rebate Amount:	\$21,160.00
Total Rebate Amount:	\$31,847.00

The information contained herein is correct as at 19 Apr 2022

OK

IMPORTANT NOTICE

- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law vers./law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Witnessed by Reporting Central
Personnel

Sketch Plan

1 2 3

Yellow box

Upper Thomson Rd

A

B

Jalan Angklong

A-SMD 212 E

B-SmL 48922

The sketch plan is drawn on a grid of graph paper. A vertical line represents 'Upper Thomson Rd' and a horizontal line represents 'Jalan Angklong'. At the intersection, there is a circled 'A' with a cross through it. Above the intersection, there is a circled 'B'. To the left of the intersection, there is a dashed line leading to a small house icon labeled 'A'. Above the intersection, there is a dashed line leading to a small box labeled 'Yellow box'. To the right of the intersection, there are two labels: 'A-SMD 212 E' and 'B-SmL 48922'. The top of the page is labeled 'Sketch Plan' and the top right corner has the numbers '1 2 3'.