

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22003832/ETY3N2**Date:** 27/05/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00061952104

Claimant Vehicle No : SKX3023H**Insured Vehicle No :** GV7172S

Date of Loss: 22/04/2022

Nature of Claim: TP

Claim No: SNM22D202774/C02/TAYHP

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SKX3023H**

Make & Model: HONDA VEZEL, 1.5 X (A)

Engine No: L15B4025990

Reg. Date: 03/12/2015 (Man. Year: 2015)

Chassis No: RU11105989

Colour: White

Odometer: 267691 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60R16

Rear Tyre Size: 215/60R16

Front Left Side: Bridgestone 4 mm

Rear Left Side: Bridgestone 4 mm

Front Right Side: Bridgestone 4 mm

Rear Right Side: Bridgestone 4 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,449.68	2,376.86	2,072.82	46.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,880.00	710.00	1,170.00	62.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,329.68	3,086.86	3,242.82	51.23
Approved Total (Overridden) (S\$)		2,450.00		
(S\$)	6,329.68	2,450.00	3,879.68	61.29
+ GST 7.00/7.00% (S\$)	443.08	171.50	271.58	61.29
Nett Amount (S\$)	6,772.76	2,621.50	4,151.26	61.29

INSPECTION

Date of Assignment: 25/04/2022

Date Inspected: 28/04/2022 Inspected At:

Accord Auto Services Pte Ltd (Bukit Merah)
BLK 1009 BUKIT MERAH LANE 3, #01-80
Singapore 159723

Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 May 2022)
Parts:	M1-SUV	HONDA VEZEL 1.5 X (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKX3023H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Broken	680.58 FL	*680.58 FL
2	2		*FRONT BUMPER SIDE RETAINER	Broken	110.00 FL	*110.00 FL
3	1		*FRONT BUMPER RH FOGLAMP GARNISH	Cut	145.00 FL	*145.00 FL
4	1		*FRONT BUMPER LOWER LIP	Not Necessary	345.60 FL	*- FL
5	1		*FRONT RH FENDER	Repair	624.57 FL	*- FL
6	1		*FRONT RH FENDER WHEEL ARCH	Cut	198.00 FL	*198.00 FL
7	1		*FRONT RH FENDER SHIELD	Not Necessary	145.00 FL	*- FL
8	1		*FRONT RH HEADLAMP	Broken	1,950.00 FL	*1,800.00 FL
9	1		*FRONT BUMPER CLIPS (SET)	Necessary	35.00 FS	*30.00 FS
10	2		*FRONT FENDER SHIELD CLIPS (SET)	Not Necessary	60.00 FS	*- FS
11	1		*RIM	Not Necessary	750.00 FS	*- FS
12	1		*TYRE	Not Necessary	245.68 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,289.43	2,963.58
- List Item Discount on L Items 20.00/20.00% (\$\$)	839.75	586.72
Total Parts (\$\$)	4,449.68	2,376.86

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAY PAINTING TO ALL AFFECTED AREAS	New	600.00	400.00
2	LABOUR REMOVE / REFIX ACCIDENT DAMAGES PARTS TO KNOCK, JACK, CUT WELD AND REALIGN ACCIDENT AFFECTED AREA	New	900.00	250.00
3	CHECK WIRING SYSTEM & LIGHT	New	100.00	30.00
4	ANTI RUST TREATMENT	New	100.00	30.00
5	TO CHECK & ADJUST WHEEL ALIGNMENT	New	100.00	0.00
6	TO REMOVE & REPLACE TYRE & RIM	New	80.00	0.00
Gross Labour Cost (\$)			1,880.00	710.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >