

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0338/2022/JT
DATE : 26-Apr-22
WIP : 21497

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 28/4/2022

YOUR INSURED VEHICLE NO : SMM 1712 A

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian

5 days - ok - Johnny Boo

2-Sep-22

OWNER'S NAME : MISS CHAN HONG CHOO
ADDRESS : 9 JALAN MATA AYER
#03-55
SINGAPORE 759153
TELEPHONE : HP +65 97835274
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : DHOM120052492000
VEHICLE NO : **SLQ 5716 D**
MODEL CODE : AUDI A4 SEDAN 1.4 TFSI S-TRONIC
MODEL YEAR : 14/7/2017
ENGINE NO : CVN 038995
CHASSIS NO : WAUZZZF44HA164740
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 23-Apr-22
PLACE OF ACCIDENT : BLK 110 YISHUN RING ROAD CAR PARK

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLQ 5716 D

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$	360.00	\$ 360.00
2	TO RENEW REAR WINDSCREEN AND 1/4 GLASS TO FACILITATE RENEWAL OF LHS REAR FENDER.	S/N \$	600.00	
3	TO CARRY OUT WATER SEEPAGE FOR REAR WINDSCREEN AND 1/4 GLASS.	S/N \$	200.00	
4	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN AND 1/4 GLASS.	S/N \$	400.00	
5	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N \$	1,400.00	
6	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$	1,400.00	
SUB-TOTAL LABOUR CHARGES		:	\$ 4,360.00	\$ 360.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLQ 5716 D

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
	<i>c/f</i>		\$ 360.00
7	TO REMOVE AND TRANSFER LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGE	S/N \$ 350.00	
8	TO DISMANTLE AND RENEW REAR BUMPER AND LHS REAR DOOR. TO CUT OUT AND WELD LHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 5,600.00	\$ 1,000.00
9	TO RESPRAY REAR BUMPER, LHS REAR FENDER, LHS REAR DOOR, DOOR HANDLE, LHS SILL PANEL, DOOR ENTRANCE, DRAIN CHANNEL, ROOF CHANNEL AND REAR END PANELLING.	\$ 5,500.00	\$ 1,750.00
10	TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT	S/N \$ 280.00	\$ 280.00
11	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		\$ 16,282.00	\$ 3,582.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLQ 5716 D

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER	1	\$ 2,609.00	\$ 2,087.20
2	REAR BUMPER FIXING PARTS	1	\$ 480.00	
3	REAR BUMPER SECURING STRIP	1	\$ 249.00	
4	REAR BUMPER GUIDE SECTION UPPER - LH	1	\$ 49.00	
5	REAR BUMPER GUIDE SECTION - LH	1	\$ 26.00	
6	REAR FENDER - LH	1	\$ 4,357.00	
7	GROMMET	1	\$ 2.00	
8	REAR WINDSCREEN	1	\$ 1,287.00	
9	QUARTER WINDOW - PH	1	\$ 685.00	
10	PRIMER	2	\$ 44.00	
11	REAR DOOR - LH	1	\$ 3,431.00	
12	REAR DOOR OUTER SEAL - LH	1	\$ 229.00	
13	BONDING AGENT	1	\$ 51.00	
14	CLEANING SOLUTION	1	\$ 74.00	
15	APPLICATOR	1	\$ 8.00	
16	REAR DOOR SEALING STRIP	1	\$ 19.00	
17	REAR DOOR CATCH - LH	1	\$ 134.00	
18	REAR DOOR HANDLE TRIM PLATE - LH	1	\$ 98.00	
19	REAR DOOR HANDLE COVER - LH	1	\$ 7.00	
20	REAR DOOR HANDLE HOUSING - LH	1	\$ 9.00	
TOTAL SPARE PARTS		:	\$ 13,848.00	\$ 2,087.20

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLQ 5716 D

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		<i>c/f</i>		<i>\$ 2,087.00</i>
21	REAR WHEEL HOUSING LINER - LH	1	\$ 260.00	
22	ALUMINIUM RIM	1	\$ 1,020.00	
23	RUBBER VALVE	1	\$ 4.00	
24	ARYLIC SEALANT	S/N	\$ 180.00	
25	CAVITY WAX	S/N	\$ 140.00	
26	STONE CHIP	S/N	\$ 180.00	
27	METAL FILLER POWDER	S/N	\$ 280.00	
28	REAR WINDSCREEN SEALANT	S/N	\$ 200.00	
29	1/4 GLASS SEALANT	S/N	\$ 100.00	
30	SUNDRIES		\$ 500.00	
TOTAL SPARE PARTS		:	\$ 16,712.00	\$ 2,087.20
TOTAL LABOUR CHARGES		:	\$ 16,282.00	\$ 3,582.00
GRAND TOTAL		:	\$ 32,994.00	\$ 5,669.20

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 bl-15/08/22



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT