

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS  
WORKSHOP : UBI ROAD 1  
CONTACT NO : 6366 2323  
FAX NO : 6841 1183  
REFERENCE : PA/TP/0338/2022/JT  
DATE : 26-Apr-22  
WIP : 21497

Xiao Tony

\$5669.20

05 days

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 28/4/2022

YOUR INSURED VEHICLE NO : SMM 1712 A

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MISS CHAN HONG CHOO  
ADDRESS : 9 JALAN MATA AYER  
#03-55  
SINGAPORE 759153  
TELEPHONE : HP +65 97835274  
TYPE OF CLAIM : THIRD PARTY CLAIM  
POLICY NO : DHOM120052492000  
VEHICLE NO : SLQ 5716 D  
MODEL CODE : AUDI A4 SEDAN 1.4 TFSI S-TRONIC  
MODEL YEAR : 14/7/2017  
ENGINE NO : CVN 038995  
CHASSIS NO : WAUZZZF44HA164740  
MILEAGE : -  
DATE IN : -  
ESTIMATED BY : JOHNNY BOO / ALLAN WU  
ACCIDENT DATE : 23-Apr-22  
PLACE OF ACCIDENT : BLK 110 YISHUN RING ROAD CAR PARK



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAJ@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLQ 5716 D**

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$ 360.00	✓
2	TO RENEW REAR WINDSCREEN AND 1/4 GLASS TO FACILITATE RENEWAL OF LHS REAR FENDER.	S/N \$ 600.00	✗
3	TO CARRY OUT WATER SEEPAGE FOR REAR WINDSCREEN AND 1/4 GLASS.	S/N \$ 200.00	✗
4	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN AND 1/4 GLASS.	S/N \$ 400.00	✗
5	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N \$ 1,400.00	✗
6	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$ 1,400.00	✗
<b>SUB-TOTAL LABOUR CHARGES</b>		<b>: \$ 4,360.00</b>	



# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLQ 5716 D

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO REMOVE AND TRANSFER LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGE	S/N \$ 350.00	K
8	TO DISMANTLE AND RENEW REAR BUMPER AND LHS REAR DOOR. TO CUT OUT AND WELD LHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 5,600.00	1000
9	✓ TO RESPRAY REAR BUMPER, LHS REAR FENDER, LHS REAR DOOR, DOOR HANDLE, LHS SILL PANEL, DOOR ENTRANCE, DRAIN CHANNEL, ROOF CHANNEL AND REAR END PANELLING.	\$ 5,500.00	1750 3 x 550 = 1650 Handle : 100. <u>1750</u>
10	TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT	S/N \$ 280.00	✓
11	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 16,282.00	





55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL : NORA.KHAJ@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLQ 5716 D**

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	REAR BUMPER <i>Rebound</i>	1	\$ 2,609.00	✓	\$2,087.20
2	REAR BUMPER FIXING PARTS <i>new</i>	1	\$ 480.00	x	
3	REAR BUMPER SECURING STRIP <i>new</i>	1	\$ 249.00	x	
4	REAR BUMPER GUIDE SECTION UPPER - LH <i>new</i>	1	\$ 49.00	x	
5	REAR BUMPER GUIDE SECTION - LH <i>new</i>	1	\$ 26.00	x	
6	REAR FENDER - LH <i>Repair</i>	1	\$ 4,357.00	+	
7	GROMMET	1	\$ 2.00	+	
8	REAR WINDSCREEN	1	\$ 1,287.00	+	
9	QUARTER WINDOW - PH	1	\$ 685.00	+	
10	PRIMER	2	\$ 44.00	+	
11	REAR DOOR - LH <i>Repair</i>	1	\$ 3,431.00	+	
12	REAR DOOR OUTER SEAL - LH	1	\$ 229.00	+	
13	BONDING AGENT	1	\$ 51.00	+	
14	CLEANING SOLUTION	1	\$ 74.00	+	
15	APPLICATOR	1	\$ 8.00	+	
16	REAR DOOR SEALING STRIP	1	\$ 19.00	+	
17	REAR DOOR CATCH - LH	1	\$ 134.00	+	
18	REAR DOOR HANDLE TRIM PLATE - LH <i>Repair new</i>	1	\$ 98.00	+	
19	REAR DOOR HANDLE COVER - LH <i>Repair</i>	1	\$ 7.00	+	
20	REAR DOOR HANDLE HOUSING - LH <i>new</i>	1	\$ 9.00	+	
<b>TOTAL SPARE PARTS</b>		:	<b>\$ 13,848.00</b>		

ALL CHARGES ARE NOT INCLUSIVE OF GST  
LEGEND: REMARKS (OK) = APPROVED. REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.



# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699  
 TEL: 6366 2323 FAX: 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLQ 5716 D

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	REAR WHEEL HOUSING LINER - LH <i>He n</i>	1	\$ 260.00	*
22	ALUMINIUM RIM <i>Est He n</i>	1	\$ 1,020.00	*
23	RUBBER VALVE	1	\$ 4.00	*
24	ARYLIC SEALANT	S/N	\$ 180.00	*
25	CAVITY WAX	S/N	\$ 140.00	*
26	STONE CHIP	S/N	\$ 180.00	*
27	METAL FILLER POWDER	S/N	\$ 280.00	*
28	REAR WINDSCREEN SEALANT	S/N	\$ 200.00	*
29	1/4 GLASS SEALANT	S/N	\$ 100.00	*
30	SUNDRIES <i>He n</i>		\$ 500.00	*X
TOTAL SPARE PARTS		:	\$ 16,712.00	
TOTAL LABOUR CHARGES		:	\$ 16,282.00	
GRAND TOTAL		:	\$ 32,994.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED. REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.






55 UBI ROAD 1, SINGAPORE 408699  
TEL: 6366 2323 FAX: 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME  
SURVEYED DATE  
AUTHORISED DATE  
EXCESS COST  
LIABILITY  
REMARKS

: Adrian  
: 28/04/22

:  
: Not Authorised, 05 Days 

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT