



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CS/LPC22003836/Evy3s2	
			Date: 23/05/2022	
			Code: LPC2	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.		Veh. Inspected	YP 8291T
	Policy No.	Z/22/VC06/112913	Coverage (\$)	0.00
	Claim No.	22/22/22/VC06/025665	Excess (\$)	700.00
	Assign From	GERALD POH	Assign Date	25/04/2022
2. Vehicle Particulars & Condition				
	Make & Model	HINO FD9JLNA	c.c	5123
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	FD9JLN10012	Colour	PURPLE
	Odometer	227983 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	235/75 R17.5	BRIDGESTONE	4 mm
	L/H Front Tyre	235/75 R17.5	BRIDGESTONE	4 mm
	R/H Rear Tyre	235/75 R17.5	BRIDGESTONE	4 mm
	L/H Rear Tyre	235/75 R17.5	BRIDGESTONE	4 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	07/04/2022	Inspection Date	26/04/2022
	Survey held at	MOVA AUTOMOTIVE PTE LTD 15 FAN YONG ROAD SINGAPORE 629792		
5a. Remarks				
	A) THE MARKET VALUE IS S\$92,000.00 (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	