

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

21/04/2022

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 The Concourse
SINGAPORE 199555.

Attention :- XA025

Page # :- 1

Veh # :- YP8291T

Veh Model :- HINO FD9JLNA 10.4 TON MT

Estimate# :- CK423236

Claim # :-

ACC. Date :- 07/04/22

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	FRONT WINDSCREEN GLASS / BR	1 PC	1,650.00	1,650.00
2.	FRONT WINDSCREEN GLASS RUBBER / CVT	1 PC	380.00	380.00
3.	FRONT WIPER PANEL / BR	1 PC	800.00	800.00
4.	FRONT WIPER ARM RH & LH / X	2 PC	100.00	200.00
5.	FRONT HANDLE GRIP / BR	1 PC	125.00	125.00
6.	FRONT WIPER LINKAGE / ?	1 PC	265.00	265.00
7.	BONNET / BR	1 PC	650.00	650.00
8.	BONNET EMBLEM - HINO / BR	1 PC	100.00	100.00
9.	BONNET EMBLEM - 500 / APC	1 PC	95.00	95.00
10.	BONNET HINGE RH & LH / X	2 PC	65.00	130.00
11.	BONNET LOCK RH & LH / X	2 PC	75.00	150.00
12.	BONNET LOCK OPENER / X	1 PC	70.00	70.00
13.	RADIATOR GRILLE / BR	1 PC	280.00	280.00
14.	RADIATOR GRILLE LOGO / BR	1 PC	150.00	150.00
15.	RADIATOR GRILLE INNER GARNISH LH / CR4	1 PC	200.00	200.00
16.	FRONT BUMPER TOP (REPAIR)	1 PC		
17.	FRONT BUMPER BOTTOM (REPAIR)	1 PC		
18.	FRONT INNER PANEL (REPAIR)	1 PC		
19.	A/C SUCTION HOSE / BT	1 PC	685.00	685.00
20.	A/C DISCHARGE HOSE / BT	1 PC	615.00	615.00
21.	A/C DISCHARGE PIPE / BT	1 PC	220.00	220.00
22.	A/C ALUMINIUM PIPE / ?	1 PC	485.00	485.00
23.	A/C COOLING COIL ASSY / ?	1 PC	3,450.00	3,450.00
24.	A/C BLOWER ASSY / ?	1 PC	1,480.00	1,480.00
25.	FRONT CABIN MOUNTING RH & LH - CHECK	2 PC		
LIST TOTAL S\$				12,180.00
15% COST PLUS S\$				1,827.00
				14,007.00
SPECIAL NET ITEMS :				
1.	FRONT WIPER BLADE RH & LH / X	2 PC	15.00	30.00
SPECIAL NET TOTAL S\$				30.00
LABOUR :				
TO KNOCK & STRAIGHTEN FRONT INNER PANEL, REMOVE & REPLACE ACCIDENT DAMAGED PARTS. REALIGN ALL CONNECTION				700 1,250.00
SPRAY PAINT BONNET, FRONT PANEL, FRONT WIPER PANEL, FRONT BUMPER				600 800.00
REMOVE & REPLACE FRONT WINDSCREEN & CHECK WATER LEAKAGE				150.00
REMOVE & REPLACE DASHBOARD ASSY, GLOVE BOX OTHER ATTACHMENT PARTS				250 300.00

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

21/04/2022

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 The Concourse
SINGAPORE 199555.

Attention :- XA025

Page # :- 1 144901

Veh # :- YP8291T

Veh Model :- HINO FD9JLNA 10.4 TON MT

Estimate# :- CK423236

Claim # :-

ACC. Date :- 07/04/22

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
	REMOVE & REPLACE A/C COOLING COIL, A/C BLOWER ASSY, PIPE, HOSE AND RECHARGE A/C GAS			150 250.00
	LABOUR TOTAL S\$			2,750.00

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$ 16,787.00

GST @ 7 % 1,175.09

AMOUNT DUE S\$ 17,962.09

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

Steve (LKK)
26/4/22, 12.30p

00- MM AL
EXCESS - 700
LIS
My AF sy
6 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

bizSAFE₃