

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

Bal. or Market Value: \_\_\_\_\_

DAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SJL 32466 Yr Regn: 24/11/08Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Stream c.c. 1799Colour Blue A/C: Insured / Std / NI / NASp. Reading 373154 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JHMRN/6840882.05166

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/60R15

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or \_\_\_\_\_

Front

Rear

R/Bal. 4 mmR/Bal. 4 mmL/Bal. 4 mmL/Bal. 4 mmD.O.A. 24/4/22D.O.I. 4/5/22Survey held at ARCDes. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV-60K

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Report Format: \_\_\_\_\_

Lump Sum / I.B.F. (\$) \_\_\_\_\_

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech. Invs (\$ \_\_\_\_\_)☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee:

Transportation:

S + RS. \$ \_\_\_\_\_

Photos

Others

TOTAL

**Automotive Repair Centre Pte Ltd**CO. Reg. No. : 201312913C  
GST Reg. No. : 201312913C**Estimate**48 Toh Guan Road East (Enterprise Hub)  
#02-146, Singapore 608586  
Tel: 64688834 Fax: 67228585  
E-mail: info@automotiverepaircentre.com.sgESTIMATE NO. : EST2204-218-TG  
DATE : 25-Apr-2022  
POLICY NO. : AIG 1900244446  
VEHICLE REG. NO. : SJL3246G  
VEHICLE MAKE : HONDA STREAM 1.8TO Motor Claim Department  
China Taiping Insurance (Singapore) Pte. Ltd  
3 Anson Road, #15-00 Springleaf Tower  
Singapore 079909  
Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

**ESTIMATE REPAIR COST**

| NO.                  | DESCRIPTION                                               | QUANTITY | UNIT COST | TOTAL COST  |
|----------------------|-----------------------------------------------------------|----------|-----------|-------------|
| <b>SPARE PARTS</b>   |                                                           |          |           |             |
| 1                    | Bonnet                                                    | 1        | \$ 680.00 | \$ 680.00   |
| 2                    | Bonnet Lock                                               | 1        | \$ 100.00 | \$ 100.00   |
| 3                    | Bonnet Insulator                                          | 1        | \$ 170.00 | \$ 170.00   |
| 4                    | Bonnet Insulator Clip                                     | 10       | \$ 5.00   | \$ 50.00    |
| 5                    | Bonnet Rubber Seal                                        | 1        | \$ 20.00  | \$ 20.00    |
| 6                    | Front Head Lamp RH                                        | 1        | \$ 680.00 | \$ 680.00   |
| 7                    | Front Head Lamp Bracket RH                                | 1        | \$ 40.00  | \$ 40.00    |
| Total Spare Parts    |                                                           |          |           | \$ 1,740.00 |
| <b>SPECIAL NETT</b>  |                                                           |          |           |             |
|                      |                                                           |          |           |             |
| Total Special Nett   |                                                           |          |           | \$ -        |
| <b>LABOUR</b>        |                                                           |          |           |             |
| 8                    | Spray Paint ( Bonnet)                                     | 1        | \$ 350.00 | \$ 350.00   |
| 9                    | Remove, Refit, Repair and Replace Accident Affected Parts | 1        | \$ 350.00 | \$ 350.00   |
| 10                   | Apply Rust Proofing on Replaced/Repaired Panel            | 1        | \$ 50.00  | \$ 50.00    |
| 11                   | Check and Rectify Electrical Wiring                       | 1        | \$ 30.00  | \$ 30.00    |
| Total Labour         |                                                           |          |           | \$ 780.00   |
| Amount Before Excess |                                                           |          |           | \$ 2,520.00 |
| Add GST @ 7%         |                                                           |          |           | 176.40      |
| Total Amount Payable |                                                           |          |           | \$ 2,696.40 |

Estimate prepared by: KenGuan

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

SPK (LKK)  
4/5/22 3:30pmM L  
L/S  
M Y  
2 4/5**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: