

48 Toh Guan Road East (Enterprise Hub)
#02-146, Singapore 608586
Tel: 64688834 Fax: 67228585
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2204-218-TG
DATE : 25-Apr-2022
POLICY NO. : AIG 1900244446
VEHICLE REG. NO. : SJL3246G
VEHICLE MAKE : HONDA STREAM 1.8

TO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road, #15-00 Springleaf Tower
Singapore 079909
Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
SPARE PARTS				
1	Bonnet	1	\$ 680.00	\$ 680.00
2	Bonnet Lock	1	\$ 100.00	\$ 100.00
3	Bonnet Insulator	1	\$ 170.00	\$ 170.00
4	Bonnet Insulator Clip	10	\$ 5.00	\$ 50.00
5	Bonnet Rubber Seal	1	\$ 20.00	\$ 20.00
6	Front Head Lamp RH	1	\$ 680.00	\$ 680.00
7	Front Head Lamp Bracket RH	1	\$ 40.00	\$ 40.00
Total Spare Parts				\$ 1,740.00
SPECIAL NETT				
Total Special Nett				\$ -
LABOUR				
8	Spray Paint (Bonnet)	1	\$ 350.00	\$ 350.00
9	Remove, Refit, Repair and Replace Accident Affected Parts	1	\$ 350.00	\$ 350.00
10	Apply Rust Proofing on Replaced/Repaired Panel	1	\$ 50.00	\$ 50.00
11	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00
Total Labour				\$ 780.00
Amount Before Excess				\$ 2,520.00
Add GST @ 7%				\$ 176.40
Total Amount Payable				\$ 2,696.40

Estimate prepared by: KenGuan

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

Total Labour \$ 780.00
Amount Before Excess \$ 2,520.00
Add GST @ 7% \$ 176.40
Total Amount Payable \$ 2,696.40

38 ✓
638
-20%
510.40
5.00
=1010.40

SPK (CLKK)
4/5/22 3:30pm

M L
L/S
M Y
2 L/S

Supp - 156
L166.40

L/S - 933-12
= 950

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

**Automotive Repair Centre Pte Ltd**

CO. Reg. No. : 201312913C
GST Reg. No. : 201312913C

Supplementary

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2204-211-TG

DATE : 4-May-2022

POLICY NO. : AIG 1900244446

VEHICLE REG. NO. : SJL3246G

VEHICLE MAKE : HONDA STREAM 1.8

TO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road, #15-00 Springleaf Tower
Singapore 079909
Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

--

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
	<u>SPARE PARTS</u>			
1	Front Grille Assy <i>[chrome only] CVT</i>	1	\$ 380.00	\$ 380.00
Total Spare Parts				\$ 380.00
Amount Before Excess				\$ 380.00
Add GST @ 7%				26.60
Total Amount Payable				\$ 406.60

*195
-20%
156*

Estimate prepared by: KenGuan

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started.