

**Automotive Repair Centre Pte Ltd**

CO. Reg. No. : 201312913C

GST Reg. No. : 201312913C

Estimate

48 Toh Guan Road East (Enterprise Hub)

#02-146, Singapore 608586

Tel: 64688834 Fax: 67228585

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2204-218-TG

DATE : 25-Apr-2022

POLICY NO. : AIG 1900244446

VEHICLE REG. NO. : SJL3246G

VEHICLE MAKE : HONDA STREAM 1.8

TO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
 3 Anson Road, #15-00 Springleaf Tower
 Singapore 079909
 Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

--

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
	<u>SPARE PARTS</u>			
1	Bonnet	1	\$ 680.00	\$ 680.00
2	Bonnet Lock	1	\$ 100.00	\$ 100.00
3	Bonnet Insulator	1	\$ 170.00	\$ 170.00
4	Bonnet Insulator Clip	10	\$ 5.00	\$ 50.00
5	Bonnet Rubber Seal	1	\$ 20.00	\$ 20.00
6	Front Head Lamp RH	1	\$ 680.00	\$ 680.00
7	Front Head Lamp Bracket RH	1	\$ 40.00	\$ 40.00
Total Spare Parts				\$ 1,740.00
	<u>SPECIAL NETT</u>			
Total Special Nett				\$ -
	<u>LABOUR</u>			
8	Spray Paint (Bonnet)	1	\$ 350.00	\$ 350.00
9	Remove, Refit, Repair and Replace Accident Affected Parts	1	\$ 350.00	\$ 350.00
10	Apply Rust Proofing on Replaced/Repaired Panel	1	\$ 50.00	\$ 50.00
11	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00

Estimate prepared by: KenGuan

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

Total Labour	\$ 780.00
Amount Before Excess	\$ 2,520.00
Add GST @ 7%	176.40
Total Amount Payable	\$ 2,696.40